



report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Green
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2025-03-24
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	36
Total items failed	15

MOT #16	2024-03-25 07:56
MOT test number	427870555971
Result	✓ Passed
Next expiry date	2025-03-24
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**MOT #15**

2024-03-06 08:42

MOT test number

198853498537

Result

✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Slight handbrake travel
- Advice** Rear Exhaust has a minor leak of exhaust gases Join (6.1.2 (a))
- Advice** Offside Front Top mount lift
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Tyre worn close to legal limit/worn on edge Approx 1.6-3 mm remaining (5.2.3 (e))
- Fail** Front Exhaust has a major leak of exhaust gases Flexi (6.1.2 (a))
- Advice** Nearside Front Top mount lift
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #14

2023-03-08 16:16

MOT test number

112883851182

Result

✓ Passed

MOT #13

2022-02-02 17:05

MOT test number

710460665395

Result

✓ Passed

**MOT #12**

2022-01-21 12:05

MOT test number

969673874124

Result**✗ Failed**

- Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Tyre has ply or cords exposed 175/65/14 (5.2.3 (d) (ii))
- Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Lower Coil spring mounting corroded and seriously weakened part of axle beam (5.3.1 (b) (i))

MOT #11

2021-02-02 12:45

MOT test number

504685133993

Result**✓ Passed****MOT #10**

2020-05-20 08:10

MOT test number

510081155211

Result**✓ Passed**

- Advice** Front Exhaust mounting defective Corroded (6.1.2 (a))
- Advice** Rear exhaust corroded
- Advice** Rear axle corroded
- Advice** Condensation in o/s/r lamp
- Advice** Rear exhaust clamp corroded/broken
- Advice** N/S/R wheel slightly binding
- Advice** Rear wiper split

**MOT #9**

2020-05-14 09:09

MOT test number

960751430887

Result**✗ Failed**

- Advice** Condensation in o/s/r lamp
- Advice** Rear exhaust clamp corroded/broken
- Fail** Nearside Front Macpherson strut mounting corroded and seriously weakened Top (5.3.3 (b) (i))
- Advice** N/S/R wheel slightly binding
- Advice** Front Exhaust mounting defective Corroded (6.1.2 (a))
- Advice** Rear wiper split
- Advice** Rear exhaust corroded
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear axle corroded
- Fail** Offside Front Macpherson strut mounting corroded and seriously weakened Top (5.3.3 (b) (i))

MOT #8

2019-05-14 14:36

MOT test number

256670213808

Result**✓ Passed**

- Advice** Exhaust corroded
- Advice** Offside Front Macpherson strut mounting corroded but not seriously weakened top plate (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear suspension components corroded
- Advice** Nearside Front Macpherson strut mounting corroded but not seriously weakened top plate (5.3.3 (b) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (2mm approx.) (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm on edges (5.2.3 (e))

**MOT #7** 2018-05-14 11:28**MOT test number** 585015843201**Result** ✓ Passed**Advice** Exhaust rusty**Advice** Rear suspension components rusty**MOT #6** 2017-05-12 13:42**MOT test number** 659264605346**Result** ✓ Passed**Advice** Rear exhaust box corroded but not leaking at time of test.**Advice** Minor surface corrosion on rear end suspension components.**MOT #5** 2016-05-09 10:33**MOT test number** 633298307047**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases rear silencer (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Rear tyres perishing on walls**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**MOT #4** 2015-05-14 10:42**MOT test number** 886154535182**Result** ✓ Passed**MOT #3** 2014-05-22 11:34**MOT test number** 459402944179**Result** ✓ Passed



MOT #2	2013-11-28 10:00
MOT test number	246402733304
Result	✓ Passed

MOT #1	2013-01-17 16:56
MOT test number	127237213013
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-23
Last registration	2024-03-25
Complete history	See info



Registration #1	2009-10-23	19 mi
Registration #2	2013-01-17	16.401 mi
Registration #3	2013-11-28	21.071 mi
Registration #4	2014-05-22	24.183 mi
Registration #5	2015-05-14	28.897 mi
Registration #6	2016-05-09	34.405 mi
Registration #7	2017-05-12	39.096 mi
Registration #8	2018-05-14	45.514 mi
Registration #9	2019-05-14	52.612 mi
Registration #10	2020-05-14	59.710 mi
Registration #11	2021-05-14	66.808 mi
Registration #12	2022-05-14	73.906 mi
Registration #13	2023-05-14	81.004 mi
Registration #14	2024-03-25	88.102 mi
Registration #15	2024-03-25	88.102 mi
Registration #16	2024-03-25	88.102 mi
Registration #17	2024-03-25	88.102 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5187434