



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Grey
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-12-24
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-21
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-20
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	19
Total items failed	1

MOT #14	2024-01-30 11:10
MOT test number	207916460838
Result	✓ Passed
Next expiry date	2025-02-20
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13	2024-01-29 15:00
MOT test number	391806943223
Result	✗ Failed
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12** 2023-02-13 11:40**MOT test number** 578800606497**Result** ✓ Passed**MOT #11** 2023-02-13 09:53**MOT test number** 226518173036**Result** ✗ Failed

**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #10** 2022-02-21 07:57**MOT test number** 394157306824**Result** ✓ Passed**MOT #9** 2022-01-13 15:52**MOT test number** 784303893001**Result** ✓ Passed

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Tyre tread unevenly worn on the inner edge. (5.2.3 (e))

**Advice** Offside Rear Nail in tyre

**Advice** Front Brake disc worn, but not excessively Both sides front brake discs lipped on the outer edges. (1.1.14 (a) (i))

**MOT #8** 2021-12-22 13:03**MOT test number** 144836009984**Result** ✗ Failed

**Advice** Front Brake disc worn, but not excessively Both sides front brake discs lipped on the outer edges. (1.1.14 (a) (i))

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Worn on the inner edge. (5.2.3 (e))

**Advice** Offside Rear Nail in tyre

**MAJOR** Nearside Front Outer Side repeater not working (4.4.1 (a) (ii))

**MOT #7** 2020-12-10 15:39**MOT test number** 311500629483**Result** ✓ Passed**MOT #6** 2019-12-05 14:09**MOT test number** 466618659720**Result** ✓ Passed**MOT #5** 2018-12-11 10:19**MOT test number** 852672986979**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2017-12-18 10:11**MOT test number** 404931452172**Result** ✓ Passed**MOT #3** 2016-11-23 11:34**MOT test number** 169058933572**Result** ✓ Passed**MOT #2** 2015-12-10 15:51**MOT test number** 103605051463**Result** ✓ Passed**MOT #1** 2015-12-10 13:00**MOT test number** 112364680872**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
20 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	20 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LO62XMX</b>
Plate since	2019-06-29
Current registration	 <b>LO62XMX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-12-21
Last registration	2024-01-30
Complete history	<a href="#">See info</a>



Registration #1	2012-12-21	16 mi
Registration #2	2015-12-10	21.780 mi
Registration #3	2015-12-10	21.780 mi
Registration #4	2016-11-23	30.294 mi
Registration #5	2017-12-18	38.040 mi
Registration #6	2018-12-11	46.428 mi
Registration #7	2019-12-05	56.006 mi
Registration #8	2020-12-10	60.482 mi
Registration #9	2020-12-10	60.482 mi
Registration #10	2020-12-10	60.482 mi
Registration #11	2020-12-10	60.482 mi
Registration #12	2020-12-10	60.482 mi
Registration #13	2020-12-10	60.482 mi
Registration #14	2020-12-10	60.482 mi
Registration #15	2020-12-10	60.482 mi
Registration #16	2020-12-10	60.482 mi
Registration #17	2020-12-10	60.482 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAYCK90899