






report date: 2024-03-28

General information

Make	FORD
Model	B-MAX TITANIUM
Colour	White
Year of manufacture	2013
Top speed	117 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 118 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-09-25


Pictures 35

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-23	
-----------------	--

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-05	
MOT pass rate	82 %	
MOT passed	9	
Failed MOT tests	2	
Total advice items	7	
Total items failed	2	

MOT #11	2024-03-04 12:26
MOT test number	838364403056
Result	✓ Passed
Next expiry date	2025-03-05

MOT #10	2023-02-28 11:19
MOT test number	763628765099
Result	✓ Passed

MOT #9	2022-03-03 14:02
MOT test number	181218514391
Result	✓ Passed

MOT #8	2021-02-22 17:13
MOT test number	560330929490
Result	✓ Passed

CarCheck.co.uk page 3/12



× Failed

MOT #7 2020-02-14 14:27

MOT test number 763238834855

Result \rightarrow Passed

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2020-02-13 10:51

MOT test number 749873033611

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #5 2019-03-06 10:29

MOT test number 272319471622

Result

✓ Passed

MOT #4 2018-02-19 10:37

MOT test number 211833236148

MOT #3 2018-02-19 10:37

MOT test number 370106683969

Result X Failed

Pass with rectification Nearside Rear passenger door cannot be opened from outside the vehicle

(6.2.B.1c)

Result

CarCheck.co.uk page 4/12



MOT #2	2017-02-13 11:53
MOT test number	380621762243
Result	✓ Passed
MOT #1	2016-02-10 09:11
MOT test number	154670902600
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	5 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK SIF
Plate since	
Current registration	UK UK
Plate since	
	Moro info

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-01
Last registration	2024-03-04
Complete history	See info



Registration #1	2013-03-01	27 mi
Registration #2	2016-02-10	16.955 mi
Registration #3	2017-02-13	21.826 mi
Registration #4	2018-02-19	25.749 mi
Registration #5	2018-02-19	25.749 mi
Registration #6	2019-03-06	29.411 mi
Registration #7	2020-02-13	32.274 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		11.777 mi

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles 2

Engine number DK03316