





General information

MakeMAZDAModel3 TSColourRedYear of manufacture2010Top speed117 mph0 - 60 mph12.2 secondsGearbox5 speed Manual		
ColourRedYear of manufacture2010Top speed117 mph0 - 60 mph12.2 seconds	Make	MAZDA
Year of manufacture 2010 Top speed 117 mph 0 - 60 mph 12.2 seconds	Model	3 TS
Top speed 117 mph 0 - 60 mph 12.2 seconds	Colour	Red
0 - 60 mph 12.2 seconds	Year of manufacture	2010
	Top speed	117 mph
Gearbox 5 speed Manual	0 - 60 mph	12.2 seconds
	Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history	
Entry 1	
Date	2021-06-19
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-12
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	10
Total items failed	7

MOT #16	2023-06-09 10:49
MOT test number	584162051990
Result	✓ Passed
Next expiry date	2024-06-12

MOT #15	2023-06-09 09:40
MOT test number	522047638966
Result	🗙 Failed
Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevent (ii))	ts the ingress of dirt (5.3.4 (b)

MOT #14		2022-06-13 07:18
MOT test	number	663677665808
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





	2022-06-13 07:18
nber	537617475179
	🗙 Failed
fside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
ectification Registration plate lamp inoperative in the case of a si	ngle lamp or all lamps
fside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
earside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
earside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
	fside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) ectification Registration plate lamp inoperative in the case of a si fside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) earside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-06-02 07:19
MOT test number	436112941801
Result	✓ Passed

MOT #11	2020-06-01 07:46
MOT test number	761249076567
Result	✓ Passed

MOT #10	2019-06-07 11:26
MOT test number	760734800588
Result	✓ Passed

МОТ #9	2019-06-07 07:43
MOT test number	372857189938
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Position lamp not working (4.2.1 (a))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	





MOT #8	2018-05-25 07:42
MOT test number	983686418500
Result	✓ Passed
MOT #7	2017-06-12 13:26
MOT test number	284248391627
Result	✓ Passed
МОТ #6	2017-02-01 13:23
MOT test number	625281844448
Result	✓ Passed
NOT #F	
MOT #5 MOT test number	2016-01-27 11:22 843457357493
Result	v Passed
Nesuit	
MOT #4	2015-02-03 11:46
MOT test number	119914435409
Result	✓ Passed
Notice Nail in offside rear tyre	
MOT #3	2014-02-11 10:29
MOT test number	656382844031
Result	✓ Passed
MOT #2	2014-02-11 10:29
MOT test number	307252844001
Result	× Failed
Pass with rectification Nearside Headlamp aim too l	ow (1.8)
Pass with rectification Offside Headlamp aim too his	gh (1.8)





MOT #1	2013-11-18 10:05
MOT test number	756212223358
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 July 2024 Tax status	12 June 2024 Valid until 1 July
Days left	64
MOT expiry date	12 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.700
Auction value	4 10.000
Average private trade value	4 11 200





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



NA60ZGB report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-26
Last registration	2023-06-09
Complete history	<u>See info</u>



Registration #1	2010-11-26	18 mi
Registration #2	2013-11-18	22.808 mi
Registration #3	2014-02-11	23.329 mi
Registration #4	2015-02-03	32.635 mi
Registration #5	2016-01-27	41.064 mi
Registration #6	2017-02-01	49.976 mi
Registration #7	2017-06-12	52.949 mi
Registration #8	2018-05-25	56.822 mi
Registration #9	2019-06-07	63.923 mi
Registration #10		11.117 esi
Registration #11		11.117 esi
Registration #12		11.777 esi
Registration #13		11.117 esi
Registration #14		11.117 esi
Registration #15		11.117 esi
Registration #16		11.117 esi
Registration #17		11.777 esi





Safety ratings

NCAP rating	****
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	2002 mm
Height	1470 mm
Length	4580 mm
Wheel base	2640 mm
Kerb weight	1235 kg
Max. allowed weight	1745 kg
Additional information	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2

Engine number

Z6 862414