



TOYOTA



AK54JNF


report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4 8 SEATS
Colour	Silver
Year of manufacture	2004
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.6 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-09-03
Pictures	30
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-06
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	16
Total items failed	5

MOT #21	2023-12-07 10:37
MOT test number	401397142559
Result	✓ Passed
Next expiry date	2024-12-06

MOT #20	2023-12-07 10:37
MOT test number	810897880058
Result	✗ Failed
Pass with rectification	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #19	2022-12-07 12:23
MOT test number	712082560829
Result	✓ Passed

MOT #18	2022-12-07 12:23
MOT test number	700828618747
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))

MOT #17	2021-12-07 16:24
MOT test number	842624057901
Result	✓ Passed

**MOT #16** 2020-09-24 13:01**MOT test number** 788336637025**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15 2019-09-27 14:02**MOT test number** 848118746953**Result** ✓ Passed

- Advice** Offside Seat belt anchorage prescribed area is corroded but not considered excessive inner sill (7.1.1 (a) (i))
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive inner sill (7.1.1 (a) (i))
- Advice** Nearside Front side step bracket badly corroded

MOT #14 2018-09-28 12:22**MOT test number** 527141536138**Result** ✓ Passed

- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** All tyres starting to crack on inner walls

MOT #13 2018-09-28 12:22**MOT test number** 679661330269**Result** ✗ Failed

- Pass with rectification** Nearside Front Inner Brake pipe excessively corroded (1.1.11 (c))
- Pass with rectification** Nearside Front Outer Brake pipe excessively corroded (1.1.11 (c))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** All tyres starting to crack on inner walls

**MOT #12** 2017-09-25 13:32**MOT test number** 645277666250**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-09-13 10:20**MOT test number** 433021387809**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded both (3.6.B.2c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pipe slightly corroded both (3.6.B.2c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2015-09-25 13:16**MOT test number** 876322220941**Result** ✓ Passed**MOT #9** 2014-09-29 14:13**MOT test number** 489502874274**Result** ✓ Passed**MOT #8** 2013-09-19 11:26**MOT test number** 118442063205**Result** ✓ Passed**MOT #7** 2012-09-20 11:33**MOT test number** 479364562268**Result** ✓ Passed

**MOT #6** 2011-09-16 11:42**MOT test number** 975189951231**Result** ✓ Passed**MOT #5** 2011-09-13 09:32**MOT test number** 475716051286**Result** ✗ Failed**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**MOT #4** 2010-09-04 09:20**MOT test number** 230597140263**Result** ✓ Passed**MOT #3** 2009-09-01 09:41**MOT test number** 390044549259**Result** ✓ Passed**MOT #2** 2008-08-26 14:25**MOT test number** 321289938416**Result** ✓ Passed**Notice** All tyres wearing on both edges**MOT #1** 2007-09-04 12:31**MOT test number** 732117347272**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	AK54JNF
Plate since	2019-03-28
Current registration	AK54JNF
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-24
Last registration	2023-12-07
Complete history	See info



Registration #1	2004-09-24	6 mi
Registration #2	2007-09-04	39.801 mi
Registration #3	2008-08-26	51.080 mi
Registration #4	2009-09-01	60.338 mi
Registration #5	2010-09-04	66.690 mi
Registration #6	2011-09-13	73.762 mi
Registration #7	2011-09-16	73.762 mi
Registration #8	2012-09-20	80.194 mi
Registration #9	2013-09-19	83.813 mi
Registration #10	2014-09-29	86.883 mi
Registration #11	2015-09-25	89.614 mi
Registration #12	2016-09-13	92.320 mi
Registration #13	2017-09-20	95.026 mi
Registration #14	2018-09-19	97.732 mi
Registration #15	2019-09-18	100.438 mi
Registration #16	2020-09-17	103.144 mi
Registration #17	2021-09-16	105.850 mi
Registration #18	2022-09-15	108.556 mi
Registration #19	2023-09-14	111.262 mi
Registration #20	2024-03-28	113.968 mi
Registration #21	2024-03-28	113.968 mi
Registration #22	2024-03-28	113.968 mi
Registration #23	2024-03-28	113.968 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Engine number	1KD1121289