



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XTR
Colour	Grey
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	173 g/km
CO2 label	H





MOT history

MOT expiry date	2024-12-06
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	54
Total items failed	5

MOT #18	2023-11-28 14:48
MOT test number	142451957415
Result	✓ Passed
Next expiry date	2024-12-06
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #17**

2023-11-23 11:23

**MOT test number**

732702846850

**Result****✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Front Tyre fouling a part of the vehicle (5.2.3 (f))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Rear Exhaust system insecure (6.1.2 (a))

**MOT #16**

2022-11-24 13:23

**MOT test number**

765380725616

**Result****✓ Passed**

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2021-11-12 13:31

**MOT test number**

709607070387

**Result**

✓ Passed

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2020-12-07 15:36

**MOT test number**

964186490797

**Result**

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH (5.3.4 (a) (i))
- Advice** UNDERSIDE SUSPENSION/SUBFRAME COMPONENTS RUSTY
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH (5.3.4 (a) (i))

**MOT #13**

2020-11-30 10:13

**MOT test number**

605888588938

**Result**

✗ Failed

- Advice** UNDERSIDE SUSPENSION/SUBFRAME COMPONENTS RUSTY
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH (5.3.4 (a) (i))
- Advice** Offside Rear Nail in tyre
- MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH (5.3.4 (a) (i))





## MOT #12

2019-05-21 08:19

MOT test number

357228063970

## Result

✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Underside suspension/subframe components rusty

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

## MOT #11

2019-05-21 08:19

MOT test number

296098601410

## Result

✗ Failed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Underside suspension/subframe components rusty

## MOT #10

2018-05-22 09:06

MOT test number

776679943039

## Result

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** ALL REAR SUSPENSION COMPONENTS RUSTY

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

## MOT #9

2017-05-25 09:23

MOT test number

138975749104

## Result

✓ Passed

**Advice** Nearside Front tyre sidewall perishing

**MOT #8** 2017-05-23 11:14**MOT test number** 293883094662**Result** ✗ Failed**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Nearside Front tyre sidewall perishing**Fail** Central Statutory seat belt missing stalk (5.1.1)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #7** 2016-05-20 08:32**MOT test number** 501390363806**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Underside of vehicle very corroded**MOT #6** 2015-04-09 14:59**MOT test number** 928559595074**Result** ✓ Passed**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2015-04-02 13:40**MOT test number** 126262295481**Result** ✗ Failed**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)**MOT #4** 2014-03-10 09:57**MOT test number** 178449264425**Result** ✓ Passed





MOT #3	2013-04-08 11:53
MOT test number	778828793052
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2	2012-03-29 10:07
MOT test number	468409782019
Result	✓ Passed
Notice	Brake pipes covered

MOT #1	2011-03-28 13:44
MOT test number	976227781098
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
6 December 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	6 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-31
Last registration	2023-11-28
Complete history	<a href="#">See info</a>



Registration #1	2008-03-31	29 mi
Registration #2	2011-03-28	67.957 mi
Registration #3	2012-03-29	74.508 mi
Registration #4	2013-04-08	82.786 mi
Registration #5	2014-03-10	92.087 mi
Registration #6	2015-04-02	101.243 mi
Registration #7	2015-04-09	101.443 mi
Registration #8	2016-05-20	105.862 mi
Registration #9	2017-05-23	108.570 mi
Registration #10	2017-05-25	108.570 mi
Registration #11	2018-05-29	111.277 mi
Registration #12	2019-05-29	111.277 mi
Registration #13	2020-05-29	111.277 mi
Registration #14	2021-05-29	111.277 mi
Registration #15	2022-05-29	111.277 mi
Registration #16	2023-05-29	111.277 mi
Registration #17	2024-05-29	111.277 mi
Registration #18	2025-05-29	111.277 mi
Registration #19	2026-05-29	111.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1640 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	1AZ0203131