



report date: 2024-03-28

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Blue
Year of manufacture	2007
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-09-29
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-25
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	32
Total items failed	8

MOT #19	2023-06-26 13:00
MOT test number	902160310781
Result	✓ Passed
Next expiry date	2024-06-25
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #18	2022-06-15 11:50
MOT test number	911806772555
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material o/s and n/s/f corroded (1.1.11 (c))
Advice	Brake pipe corroded, covered in grease or other material both rear (1.1.11 (c))
Advice	Rear tyres cracking not excessive

**MOT #17**

2022-06-14 08:14

MOT test number

609465508931

Result**✗ Failed**

- Advice** Exhaust mounting defective exhaust front downpipe flexi separating (6.1.2 (a))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material o/s and n/s/f corroded (1.1.11 (c))
- Advice** Rear tyres cracking not excessive
- Fail** Exhaust system insecure exhaust rear back box bracket corroded off and knocking (6.1.2 (a))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material both rear (1.1.11 (c))

MOT #16

2021-06-21 09:46

MOT test number

624119434695

Result**✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust heatshield loose/corroded
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear axles bushes slight wear
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear tyres slight cracking
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear springs corroded
- Advice** Rear Exhaust silencer slightly loose (8.1.1 (b) (i))

**MOT #15** 2020-06-09 10:54**MOT test number** 317042810901**Result** ✓ Passed**MOT #14** 2020-06-09 10:54**MOT test number** 120094807823**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**MOT #13** 2019-03-26 11:23**MOT test number** 742518086469**Result** ✓ Passed**MOT #12** 2019-03-26 10:15**MOT test number** 547153463219**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2018-04-19 12:24**MOT test number** 377064044629**Result** ✓ Passed**MOT #10** 2018-04-19 12:24**MOT test number** 237366156971**Result** ✗ Failed**Pass with rectification** Central Front Obligatory mirror insecure (8.1.1)

**MOT #9** 2017-04-25 10:53**MOT test number** 805831021930**Result** ✓ Passed**Advice** Nearside rear tyre cracked and perished**Advice** Offside rear tyre cracked and perished**MOT #8** 2017-04-25 10:53**MOT test number** 284259407575**Result** ✗ Failed**Advice** Nearside rear tyre cracked and perished**Advice** Offside rear tyre cracked and perished**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #7** 2016-01-25 09:59**MOT test number** 370855685799**Result** ✓ Passed**MOT #6** 2014-09-23 12:58**MOT test number** 106086864247**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Tyre pressuers and rear brake linings not check**Notice** Unable to check wheel nuts and outer wheel rims due to trims fitted

**MOT #5** 2014-09-23 12:58**MOT test number** 126406164277**Result** ✗ Failed**Pass with rectification** Rear fog lamp not working (1.3.2b)**Notice** Unable to check wheel nuts and outer wheel rims due to trims fitted**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Tyre pressuers and rear brake linings not check**MOT #4** 2013-10-07 10:16**MOT test number** 229880983258**Result** ✓ Passed**MOT #3** 2012-10-02 11:56**MOT test number** 347306772216**Result** ✓ Passed**MOT #2** 2011-10-06 14:41**MOT test number** 405199671259**Result** ✓ Passed**MOT #1** 2010-10-08 10:25**MOT test number** 322571080437**Result** ✓ Passed**Advice** Offside Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
25 June 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	KF57MKZ
Plate since	2019-03-28
Current registration	KF57MKZ
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-08
Last registration	2023-06-26
Complete history	See info



Registration #1	2007-10-08	9 mi
Registration #2	2010-10-08	9.896 mi
Registration #3	2011-10-06	29.198 mi
Registration #4	2012-10-02	38.208 mi
Registration #5	2013-10-07	44.248 mi
Registration #6	2014-09-23	51.023 mi
Registration #7	2016-01-25	51.572 mi
Registration #8	2017-04-25	54.091 mi
Registration #9	2017-04-25	54.091 mi
Registration #10	2018-04-19	56.560 mi
Registration #11	2019-06-20	59.377 mi
Registration #12	2020-06-20	59.377 mi
Registration #13	2021-06-20	59.377 mi
Registration #14	2022-06-20	59.377 mi
Registration #15	2023-06-20	59.377 mi
Registration #16	2024-06-20	59.377 mi
Registration #17	2025-06-20	59.377 mi
Registration #18	2026-06-20	59.377 mi
Registration #19	2027-06-20	59.377 mi
Registration #20	2028-06-20	59.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7L05452