




report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Black
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





**Internet history**

**Entry 2**

Date	2021-07-06
Pictures	34
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)

**Entry 1**

Date	2021-07-06
Pictures	34
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](http://autotrader.co.uk)



MOT history

MOT expiry date	2024-08-03
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	36
Total items failed	10

MOT #16 2023-08-02 12:32

MOT test number 445988188728

Result ✔ Passed

Next expiry date 2024-08-03

**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output unit damp inside (4.1.4 (b))

MOT #15 2022-08-04 11:57

MOT test number 685593527299

Result ✔ Passed

**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



<b>MOT #14</b>	2022-07-29 11:15
<b>MOT test number</b>	684015485685
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Rear Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))
<b>Advice</b>	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Advice</b>	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

<b>MOT #13</b>	2021-08-04 13:17
<b>MOT test number</b>	446302208775
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

<b>MOT #12</b>	2021-01-07 17:28
<b>MOT test number</b>	354711417843
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))



MOT #11 2021-01-07 11:02

MOT test number 573342010425

Result ✗ Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

**Fail** Offside Rear Lower Suspension arm pin or bush excessively worn front outer bolt (5.3.4 (a) (i))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Rear Upper Suspension arm pin or bush excessively worn outer bolt (5.3.4 (a) (i))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #10 2020-01-07 17:05

MOT test number 580963745799

Result ✓ Passed

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Rear Nail in tyre

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



**MOT #9** 2020-01-07 11:12

**MOT test number** 705122914605

**Result** ✗ Failed

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Nail in tyre
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #8** 2019-01-12 10:59

**MOT test number** 414951320005

**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



**MOT #7** 2019-01-12 09:46

**MOT test number** 330628445254

**Result** ✗ Failed

- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2018-01-04 12:03

**MOT test number** 183695424660

**Result** ✓ Passed

- Advice** Nearside rear tyre worn uneven on inner edge
- Advice** Slight damage to offside rear tyre inner sidewall and worn uneven on inner edge

**MOT #5** 2017-01-10 16:40

**MOT test number** 321821338977

**Result** ✓ Passed

**MOT #4** 2016-04-22 08:58

**MOT test number** 664716197670

**Result** ✓ Passed

**MOT #3** 2015-04-20 09:17

**MOT test number** 297790115148

**Result** ✓ Passed

- Notice** Both rear tyres worn on the inner edge



**MOT #2** 2014-05-10 08:35

**MOT test number** 217954934170

**Result** ✓ Passed

**MOT #1** 2013-05-08 15:37

**MOT test number** 899568323171

**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 April 2025

✓  
**MOT**

**Expires:**  
3 August 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	3 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




**Damage history**

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	EXAMPLE
<b>Category</b>	EXAMPLE
<b>Type</b>	EXAMPLE



**Damage 2**

<b>Date</b>	EXAMPLE
<b>Category</b>	EXAMPLE
<b>Type</b>	EXAMPLE



**Extra FORD salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>EA10TWV</b>
Plate since	2019-09-29
Current registration	<b>EA10TWV</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-05-11
Last registration	2023-08-02
Complete history	<a href="#">See info</a>



Registration #1	2010-05-11	11 mi
Registration #2	2013-05-08	20.961 mi
Registration #3	2014-05-10	31.502 mi
Registration #4	2015-04-20	42.684 mi
Registration #5	2016-04-22	51.745 mi
Registration #6	2017-01-10	57.810 mi
Registration #7	2018-01-04	69.704 mi
Registration #8	2019-01-12	82.685 mi
Registration #9	2019-01-12	82.685 mi
Registration #10	2020-01-07	97.057 mi
Registration #11	2020-01-07	97.057 mi
Registration #12	2020-01-07	97.057 mi
Registration #13	2020-01-07	97.057 mi
Registration #14	2020-01-07	97.057 mi
Registration #15	2020-01-07	97.057 mi
Registration #16	2020-01-07	97.057 mi
Registration #17	2020-01-07	97.057 mi
Registration #18	2020-01-07	97.057 mi
Registration #19	2020-01-07	97.057 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1500 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1587 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

AU19126