



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SPORT S40
Colour	Blue
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.2 mpg
CO2 emission	176 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-06-20
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-06-25
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	29
Total items failed	2

MOT #14	2023-06-26 14:04
MOT test number	922734042072
Result	✓ Passed
Next expiry date	2024-06-25
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #13	2022-06-21 14:15
MOT test number	367740245507
Result	✓ Passed

MOT #12	2021-09-27 09:34
MOT test number	628548555495
Result	✓ Passed

MOT #11	2020-10-08 12:55
MOT test number	208034765823
Result	✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a))

**MOT #10** 2020-10-08 10:43**MOT test number** 748625483810**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a))**Fail** Windscreen washer not working (3.5 (a))**MOT #9** 2019-10-15 09:10**MOT test number** 661765017418**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2018-10-16 14:51**MOT test number** 551623382184**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner (5.2.3 (e))**Advice** Offside Rear Upper position bulb inop**MOT #7** 2017-10-10 10:20**MOT test number** 239831757744**Result** ✓ Passed**Advice** Nearside Front tyre wearing on inner**Advice** Offside Front tyre worn close to cord on inner tread**Advice** Offside Rear tyre wearing on inner tread**Advice** Engine and underside covers fitted not allowing full inspection

**MOT #6** 2017-10-10 09:04**MOT test number** 650448863488**Result** ✗ Failed

- Advice** Offside Front tyre worn close to cord on inner tread
- Advice** Offside Rear tyre wearing on inner tread
- Advice** Engine and underside covers fitted not allowing full inspection
- Advice** Nearside Front tyre wearing on inner
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #5 2016-10-14 08:43**MOT test number** 562893616624**Result** ✓ Passed

- Advice** Engine and underside covers fitted not allowing full inspection
- Advice** O/s/f tyre wearing on inner tread
- Advice** N/s/f outer marker bulb inop

MOT #4 2015-10-14 08:09**MOT test number** 410439972641**Result** ✓ Passed

- Advice** Wipers smearing
- Advice** Engine and under trays fitted not allowing full inspection

**MOT #3** 2014-10-03 09:58**MOT test number** 716266074205**Result** ✓ Passed

Advice Offside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Under-trays fitted obscuring some underside components

Notice Wipers smearing but not obscuring view

Notice Engine covers fitted obscuring some components in the engine bay

MOT #2 2013-10-18 09:30**MOT test number** 257091693255**Result** ✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Nsf and Osf tyres perished on sidewalls

Notice Engine covers fitted obscuring some components in the engine bay

MOT #1 2012-09-24 14:16**MOT test number** 955948962216**Result** ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DE59XDP
Plate since	2024-03-29
Current registration	DE59XDP
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-16
Last registration	2023-06-26
Complete history	See info



Registration #1	2009-10-16	20 mi
Registration #2	2012-09-24	26.710 mi
Registration #3	2013-10-18	35.414 mi
Registration #4	2014-10-03	44.182 mi
Registration #5	2015-10-14	54.473 mi
Registration #6	2016-10-14	63.006 mi
Registration #7	2017-10-10	71.309 mi
Registration #8	2017-10-10	71.310 mi
Registration #9	2019-06-20	75.377 mi
Registration #10	2019-06-20	75.377 mi
Registration #11	2019-06-20	75.377 mi
Registration #12	2019-06-20	75.377 mi
Registration #13	2019-06-20	75.377 mi
Registration #14	2019-06-20	75.377 mi
Registration #15	2019-06-20	75.377 mi
Registration #16	2019-06-20	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1384 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	152350