





General information

MakeBMWModelX6 XDRIVE30DColourRedYear of manufacture2008		
Colour Red	Make	BMW
	Model	X6 XDRIVE30D
Year of manufacture 2008	Colour	Red
	Year of manufacture	2008
Top speed130 mph	Top speed	130 mph
0 - 60 mph 8.0 seconds	0 - 60 mph	8.0 seconds
Gearbox 6 speed automatic	Gearbox	6 speed automatic

Engine & fuel consumption

Power	232 BHP
Max. torque	520 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	40.4 mpg
Consumption combined	34.4 mpg
CO2 emission	217 g/km
CO2 label	К







Internet history

Entry 1	
Date	2021-10-07
Pictures	13
Listing price	<u>View report</u>









source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-02
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	42
Total items failed	7

MOT #17	2023-08-03 08:50
MOT test number	494144932495
Result	✓ Passed
Next expiry date 2024-08	
Advice No acceleration detected(no printout)	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #16		2023-08-02 12:18
MOT test	number	748302252146
Result		🗙 Failed
Advice	No acceleration detected(no printout)	
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #15	2022-01-15 12:13
MOT test number	672910096600
Result	✓ Passed

MOT #14	2020-11-13 18:38
MOT test number	159672049865
Result	✓ Passed





MOT #13		2019-10-23 11:28
MOT test	number	651514697314
Result		✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12		2018-10-22 14:52
MOT test	number	548494796152
Result		✓ Passed
Advice	Rear number plate deteriorated	
Advice	Front Brake pad(s) wearing thin 5000 miles (1.1.13 (a) (ii))	
Advice	Front number plate cable tied on	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14	4 (a) (ii))





MOT #11		2018-10-22 09:42
MOT test	number	965864274120
Result		🗙 Failed
MAJOR (5.3.4 (b)	Nearside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the (ii))	ingress of dirt
Advice	Front Brake pad(s) wearing thin 5000 miles (1.1.13 (a) (ii))	
Advice	Rear number plate deteriorated	
DANGER Bridgestor	ROUS Offside Front Tyre tread depth below requirements of 1.6mm 275/40/20 ne (5.2.3 (e))	0 106 W R/F
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR	Nearside Inner Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Front number plate cable tied on	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Lipped (1	.1.14 (a) (ii))
Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3	3.4 (b) (i))
DANGER Bridgestor	ROUS Nearside Front Tyre tread depth below requirements of 1.6mm 275/40/ ne (5.2.3 (e))	20 106 W R/F
MAJOR	Offside Headlamp not working on main beam (4.1.1 (a) (ii))	

MOT #10		2017-10-24 10:46
MOT test	number	662213254805
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	



MOT #9		2016-10-21 14:20
MOT test	number	549880910925
Result		✓ Passed
Advice	Rear number plate deteriorating	
Advice	Rear Brake pad(s) wearing thin Approx 5000 miles remaining (3.5.1g)	
Advice	Front number plate slightly insecure	
MOT #8		2016-10-21 10:14
MOT test	number	727405007019
Result		🗙 Failed
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 315/35/20 106w R/F Bridgestone (4.1.D.1a)		
Advice	Rear number plate starting to deteriorate	
Advice	Rear Brake pad(s) wearing thin Approx 5000 miles remaining (3.5.1g)	
FailOffside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords315/35/20 106w R/F Bridgestone (4.1.D.1a)		

Front number plate slightly insecure Advice

MOT #7		2015-12-21 17:19
MOT test	number	683832804916
Result		✓ Passed
Advice Nearside Front Lower Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)		
Advice Offside Front Tyre worn close to the legal limit scrubbed on edges (4.1.E.1)		.E.1)
Advice	Nearside Front Tyre worn close to the legal limit scrubbed bold on edge	es (4.1.E.1)





MOT #6	2015-12-21 12:16
MOT test number	520582441065
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Rear Exhaust system not adequately supported (7.1.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2014-12-22 12:03
MOT test number	468126154436
Result	✓ Passed

МОТ #4	2013-12-20 13:42
MOT test number	346974353381
Result	✓ Passed

MOT #3	2013-12-19 13:04	
MOT test number	908813953363	
Result	🗙 Failed	
Pass with rectification Nearside Headlamp aim too low (1.8)		
Fail Nearside Headlamp cleaning device inoperative (1.7.2)		
Fail Brake fluid warning lamp illuminated (3.6.G.2)		
Advice Rear Brake pad(s) wearing thin (3.5.1g)		
Fail Offside Headlamp cleaning device inoperative (1.7.2)		

M111HNT

report date: 2024-03-28



M111HNT report date: 2024-03-28

MOT #2	2012-12-19 15:01
MOT test number	725924152353
Result	✓ Passed
AdviceNearside Rear Tyre worn close to the legal limit (4.1.E.1)AdviceOffside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #1	2011-12-14 15:56

MOT test number

MOT test nu	umber	496478141448
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 2 August 2024
Tax status	Valid until 1 January
Days left	247
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	A.F.
Category	ante.
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this BMW had different number plate	5.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-12-19
Last registration	2023-08-03
Complete history	See info



Registration #1	2008-12-19	28 mi
Registration #2	2011-12-14	17.698 mi
Registration #3	2012-12-19	26.033 mi
Registration #4	2013-12-19	32.058 mi
Registration #5	2013-12-20	32.058 mi
Registration #6	2014-12-22	38.857 mi
Registration #7	2015-12-21	46.600 mi
Registration #8	2015-12-21	46.603 mi
Registration #9	2016-10-21	54.176 mi
Registration #10	2016-10-21	54.176 mi
Registration #11		11.117 mi
Registration #12		11.117 est
Registration #12 Registration #13		01.000 est 01.000 est
		01,000 est 01,000 est 01,000 est
Registration #13		01,000 est 01,000 est 01,000 est 01,000 est
Registration #13 Registration #14		0.000 es
Registration #13 Registration #14 Registration #15		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es
Registration #13 Registration #14 Registration #15 Registration #16		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

Number of axles CarCheck.co.uk

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1983 mm
Height	1690 mm
Length	4877 mm
Wheel base	2933 mm
Max. allowed weight	2675 kg
Additional information	
Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	4

2

Engine number

22386887