



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS D-4D TR TOURER
Colour	Silver
Year of manufacture	-
Top speed	200 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	300 Nm at 2.400 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-28
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #20	2023-02-21 16:16
MOT test number	126830413772
Result	✓ Passed
Next expiry date	2024-02-28
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear suspension corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	General corrosion underside

MOT #19	2023-02-17 16:10
MOT test number	210308286402
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	General corrosion underside
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear suspension corroded

MOT #18	2022-02-16 10:05
MOT test number	420932085179
Result	✓ Passed
Advice	Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Rear Brake cable damaged but not to excess (1.1.15 (a))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Child Seat fitted not allowing full inspection of adult belt
Advice	General corrosion underside

**MOT #17** 2021-01-30 12:54**MOT test number** 823874658241**Result** ✓ Passed**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** All rear suspension components**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #16** 2021-01-29 13:23**MOT test number** 174999363861**Result** ✗ Failed**Advice** All rear suspension components**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Suspension arm corroded and seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #15** 2020-02-29 12:26**MOT test number** 838758949003**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2020-02-28 12:56

MOT test number

440194212564

Result**✗ Failed****Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #13**

2019-02-12 17:56

MOT test number

470020705333

Result**✓ Passed****Advice** Suspension arms/subframes corroded**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2019-02-07 12:06

MOT test number

425251916403

Result**✗ Failed****Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Suspension arms/subframes corroded

**MOT #11** 2018-02-26 12:54**MOT test number** 149314797016**Result** ✓ Passed**Advice** Handbrake travel long**MOT #10** 2018-02-23 13:22**MOT test number** 518137565988**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Handbrake travel long**MOT #9** 2017-02-25 11:40**MOT test number** 591303869415**Result** ✓ Passed**Advice** Rear Brake pads wearing thin**Advice** Front Brake pads wearing thin**MOT #8** 2017-02-25 10:53**MOT test number** 581561217675**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Rear Brake pads wearing thin**Advice** Front Brake pads wearing thin**Fail** Offside Rear Stop lamp not working (1.2.1b)

**MOT #7** 2016-02-26 12:45**MOT test number** 482080428127**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Both handbrake cables worn through outer sheath on brackets
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit edges also wearing very thin (4.1.E.1)
- Advice** Nearside Rear slight bind when spun by hand

MOT #6 2016-02-26 12:45**MOT test number** 859778127303**Result** ✗ Failed

- Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)
- Advice** Offside Front Tyre worn close to the legal limit edges also wearing very thin (4.1.E.1)
- Advice** Both handbrake cables worn through outer sheath on brackets
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Pass with rectification** Offside Rear Direction indicators incorrect colour (1.4.A.2f)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear slight bind when spun by hand
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #5 2015-02-26 15:05**MOT test number** 327137055007**Result** ✓ Passed

**MOT #4** 2014-05-08 11:23**MOT test number** 446288324100**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2013-05-10 09:33**MOT test number** 969590533122**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-05-31 13:02**MOT test number** 258892152174**Result** ✓ Passed**MOT #1** 2011-05-27 16:28**MOT test number** 496547841130**Result** ✓ Passed



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-05-30
Last registration	2023-02-21
Complete history	See info



Registration #1	2008-05-30	11 mi
Registration #2	2011-05-27	43.909 mi
Registration #3	2012-05-31	54.332 mi
Registration #4	2013-05-10	65.683 mi
Registration #5	2014-05-08	79.851 mi
Registration #6	2015-02-26	90.954 mi
Registration #7	2016-02-26	99.547 mi
Registration #8	2016-02-26	99.547 mi
Registration #9	2017-02-25	109.142 mi
Registration #10	2017-02-25	109.142 mi
Registration #11	2018-02-23	122.488 mi
Registration #12	2019-05-29	131.277 mi
Registration #13	2019-05-29	131.277 mi
Registration #14	2019-05-29	131.277 mi
Registration #15	2019-05-29	131.277 mi
Registration #16	2019-05-29	131.277 mi
Registration #17	2019-05-29	131.277 mi
Registration #18	2019-05-29	131.277 mi
Registration #19	2019-05-29	131.277 mi
Registration #20	2019-05-29	131.277 mi
Registration #21	2019-05-29	131.277 mi
Registration #22	2019-05-29	131.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1525 mm
Length	4715 mm
Wheel base	2700 mm
Kerb weight	1380 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4425411063