





report date: 2024-03-28

General information

Make	NISSAN
Model	NV200 DCI ACENTA COMBI
Colour	Black
Year of manufacture	2014
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	131 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-02-15

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-30
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	19
Total items failed	0

MOT #12	2024-03-26 08:39
MOT test number	972443016400
Result	✓ Passed
Next expiry date	2025-03-30

MOT #11		2024-03-21 11:29
MOT test number	er	981654850651
Result		× Failed
DANGEROUS	Offside Rear Brakes imbalanced across an axle by more than 50% (1.2.)	1 (b) (ii))

MOT #10	2023-03-20 13:41
MOT test number	913545863219
Result	✓ Passed
MOT #9	2022-03-31 15:04
MOT test number	861823291145
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #8 2022-03-30 11:17

MOT test number 824944087084

Result X Failed

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4

(b) (ii))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2021-10-06 16:05

MOT test number 828014535372

Result \rightarrow Passed

MOT #6 2021-10-05 11:58

MOT test number 684066363589

Result X Failed

MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen

(3.5(a))

MOT #5 2020-01-14 17:38

MOT test number 155549091380

Result \rightarrow Passed

CarCheck.co.uk page 4/12



(i))

PE14EYU

report date: 2024-03-28

✓ Passed

MOT test number

380012312534

Result

MAJOR Offside Front Direction indicator incorrect colour (4.4.3 (a))

MAJOR Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

MAJOR Offside Headlamp aim too high (4.1.2 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b))

MOT #3

MOT test number

806333938245

Result

✓ Passed

MOT #2

2019-01-22 15:08

MOT test number 858562528447

Result X Failed

MAJOR Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

 MOT #1
 2018-01-20 17:22

 MOT test number
 170748270763

Advice Rear B

Result

Rear Both drop links have slight play

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	30 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CONTRACTOR CONT	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	AIZ SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-12
Last registration	2024-03-26
Complete history	See info



Registration #1	2014-03-12	21 mi
Registration #2	2018-01-20	49.543 mi
Registration #3	2019-01-22	65.265 mi
Registration #4	2019-01-23	65.265 mi
Registration #5	2020-01-14	73.690 mi
Registration #6	2020-01-14	73.693 mi
Registration #7	2021-10-05	89.685 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	75%
Children	80%
Pedestrian	60%
Safety systems	38%
Overall rating	65%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Max. allowed weight	2050 kg

Additional information

Number of seats	7
Number of axles	2
Engine number	169208

CarCheck.co.uk page 12/12