





report date: 2024-03-29

# General information

Make	TOYOTA
Huke	10101A
Model	MR2 ROADSTER
Colour	Red
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	138 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	178 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-10-16


Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

# MOT history

MOT expiry date	2024-10-17
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	21
Total items failed	4

MOT #17	2023-10-18 08:38
MOT test number	102082930263
Result	✓ Passed
Next expiry date	2024-10-17

MOT #16	2022-10-10 16:16
MOT test number	156890928688
Result	<b>✓</b> Passed
Advice Handbrake lever travel	

MOT #15	2022-10-08 14:41
MOT test number	952767485089
Result	<b>X</b> Failed
Fail Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))  Advice Handbrake lever travel	

MOT #14		2021-10-12 15:19
MOT test	number	579882654439
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #13** 2021-10-06 13:23 **MOT** test number 198095846413 Result **X** Failed Fail Offside Rear Service brake excessively binding (1.2.1 (f)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2018-12-20 15:58

MOT test number 998633506353

Result ✓ Passed

MOT #10

MOT test number

376556173106

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

494757565471

Result

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear worn on inner edge

MOT #8

MOT test number

Result

Advice Parking brake lever has little reserve travel (3.1.6b)

MOT #7

MOT test number

148853754384

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)

Notice Condensation in nearside rear lamp

 MOT #5
 2012-12-05 12:39

 MOT test number
 289740142326

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



Fail

**GP56MXW** 

report date: 2024-03-29

MOT #4	2011-12-02 09:47
MOT test number	555966731302
Result	<b>✓</b> Passed
MOT #3	2010-12-08 11:58
MOT test number	872352040397
Result	<b>✓</b> Passed
MOT #2	2009-12-11 10:47
MOT test number	921595849392
Result	✓ Passed
MOT #1	2009-12-11 10:29
MOT test number	304225749372
Result	<b>×</b> Failed

Parking brake: efficiency below requirements (3.7.B.7)

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	17 October 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

$\sim$		h:a	+
-C)V	vner	mis	$\mathbf{I}$

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u> .	A
nave: eneck it in the premium report and see all owner registrations. Download the fair report <u>nere</u> .	
THE STATE OF THE S	
***************************************	
**************************************	
More info	•
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
NP_	
NAME OF THE PROPERTY OF THE PR	
Plate since	
TK STEE	
Plate since	
More info	•

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-12-13
Last registration	2023-10-18
Complete history	See info



Registration #1	2006-12-13	22 mi
Registration #2	2009-12-11	14.636 mi
Registration #3	2009-12-11	14.636 mi
Registration #4	2010-12-08	20.279 mi
Registration #5	2011-12-02	26.648 mi
Registration #6	2012-12-05	32.966 mi
Registration #7	2013-12-06	39.082 mi
Registration #8	2014-12-19	46.000 mi
Registration #9	2015-12-11	51.908 mi
Registration #10	2016-12-09	58.026 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1695 mm
Height	1240 mm
Length	3885 mm
Wheel base	2450 mm
Kerb weight	960 kg
Max. allowed weight	1225 kg

# Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	1ZZ2357267

CarCheck.co.uk page 13/13