



OU57XNX

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Black
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-01-14
Pictures	32
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-30
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	43
Total items failed	8

MOT #17	2023-07-31 14:03
MOT test number	325498761638
Result	✓ Passed
Next expiry date	2024-07-30
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16	2021-08-16 14:16
MOT test number	955058284374
Result	✓ Passed
Advice	Offside Rear Drag link end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Shock absorbers has slight external damage to the casing N/S/R and O/S/R shock dust cover perished (5.3.2 (b))

**MOT #15**

2021-08-16 10:46

MOT test number

528034912936

Result

✗ Failed

Minor

Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened N/S/F and O/S/F (1.1.14 (a) (ii))

Fail

Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Rear Brake pad(s) wearing thin N/S/R and O/S/R (1.1.13 (a) (ii))

Advice

Offside Rear Drag link end ball joint has slight play (2.1.3 (b) (i))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened N/S/R and O/S/R (1.1.14 (a) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Rear Shock absorbers has slight external damage to the casing N/S/R and O/S/R shock dust cover perished (5.3.2 (b))

MOT #14

2020-08-17 13:18

MOT test number

536298066625

Result

✓ Passed

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2019-08-16 11:13

MOT test number

222111927841

Result

✓ Passed

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened Offside & Nearside (1.1.14 (a) (ii))

**MOT #12** 2018-08-30 14:19**MOT test number** 888405362462**Result** ✓ Passed

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

MOT #11 2018-08-30 09:01**MOT test number** 452173962621**Result** ✗ Failed

- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10 2017-08-07 09:07**MOT test number** 389310465346**Result** ✓ Passed

- Advice** Both rear bump stops fallen down
- Advice** Rear brake discs poor condition

**MOT #9** 2016-08-11 15:17**MOT test number** 902207380610**Result** ✓ Passed**Advice** Both rear bump stops perishing**Advice** Handbrake cables deteriorating**Advice** Rear tyres feathering**MOT #8** 2015-08-27 09:35**MOT test number** 250850010214**Result** ✓ Passed**Advice** Offside Rear tread low**MOT #7** 2014-08-05 17:58**MOT test number** 555677114232**Result** ✓ Passed**Notice** Both rear bump stops slightly perished**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Requires oil top up**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-08-04 10:25**MOT test number** 245156714225**Result** ✗ Failed**Fail** Nearside Headlamp aim too low and too far to the right. (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear bump stops slightly perished**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Requires oil top up**MOT #5** 2013-08-07 10:41**MOT test number** 399029913205**Result** ✓ Passed**MOT #4** 2012-08-16 17:08**MOT test number** 757739322269**Result** ✓ Passed**MOT #3** 2011-08-24 11:04**MOT test number** 565566531251**Result** ✓ Passed**Notice** Rear tyres bald on inner edges**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2010-08-16 14:34**MOT test number** 253028320249**Result** ✓ Passed**Notice** Both rear tyre's started feathering on inner edge's slightly



MOT #1	2010-08-16 13:22
MOT test number	304268420436
Result	✗ Failed
Notice	Both rear tyre's started feathering on inner edge's slightly
Fail	Nearside Side repeater not working (1.4.A.2c)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	30 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 OU57XNX
Plate since	2019-03-29
Current registration	 OU57XNX
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-01
Last registration	2023-07-31
Complete history	See info



Registration #1	2007-09-01	23 mi
Registration #2	2010-08-16	29.024 mi
Registration #3	2010-08-16	29.024 mi
Registration #4	2011-08-24	39.385 mi
Registration #5	2012-08-16	46.902 mi
Registration #6	2013-08-07	56.176 mi
Registration #7	2014-08-04	67.763 mi
Registration #8	2014-08-05	67.763 mi
Registration #9	2015-08-27	77.817 mi
Registration #10	2016-08-11	85.296 mi
Registration #11	2016-08-11	85.296 mi
Registration #12	2016-08-11	85.296 mi
Registration #13	2016-08-11	85.296 mi
Registration #14	2016-08-11	85.296 mi
Registration #15	2016-08-11	85.296 mi
Registration #16	2016-08-11	85.296 mi
Registration #17	2016-08-11	85.296 mi
Registration #18	2016-08-11	85.296 mi
Registration #19	2016-08-11	85.296 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

NOT KNOWN