



report date: 2024-03-29

General information

Make	CITROEN
Model	SAXO FORTE
Colour	Blue
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	88 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-04
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #25</b>	2021-04-12 13:50
<b>MOT test number</b>	419793620797
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-04-11

<b>MOT #24</b>	2021-04-06 10:30
<b>MOT test number</b>	357721688133
<b>Result</b>	✗ Failed
<b>Fail</b> Offside Driver's door cannot be opened from outside the vehicle (6.2.3 (a))	
<b>Fail</b> Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
<b>Fail</b> Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))	

<b>MOT #23</b>	2020-05-27 10:28
<b>MOT test number</b>	830369230026
<b>Result</b>	✓ Passed
<b>Advice</b> Front Tyre slightly damaged/cracking or perishing offside and nearside (5.2.3 (d) (ii))	

<b>MOT #22</b>	2019-05-30 10:38
<b>MOT test number</b>	827499115536
<b>Result</b>	✓ Passed
<b>Advice</b> Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Advice</b> Front Tyre slightly damaged/cracking or perishing offside and nearside (5.2.3 (d) (ii))	

<b>MOT #21</b>	2018-05-10 12:02
<b>MOT test number</b>	554687366679
<b>Result</b>	✓ Passed
<b>Advice</b> Oil leak	

**MOT #20** 2017-05-31 12:41**MOT test number** 173243924311**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Items removed from driver's view prior to test**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #19** 2017-05-30 10:25**MOT test number** 314481354568**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Items removed from driver's view prior to test**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Central Exhaust system not adequately supported rubber hanger missing (7.1.1)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #18** 2016-05-17 13:05**MOT test number** 157695163610**Result** ✓ Passed**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**MOT #17**

2016-05-17 12:22

**MOT test number**

685740592424

**Result****✗ Failed**

- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Rear fog lamp not working (1.3.2b)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Stop lamp not working (1.2.1b)

**MOT #16**

2015-06-03 11:14

**MOT test number**

315694455123

**Result****✓ Passed**

- Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)
- Notice** Exhaust mounting rubber missing but exhaust still supported
- Notice** Exhaust back box in poor condition

**MOT #15**

2015-06-02 10:01

**MOT test number**

778673555106

**Result****✗ Failed**

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Exhaust mounting rubber missing but exhaust still supported
- Notice** Exhaust back box in poor condition
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**MOT #14** 2014-05-21 16:28**MOT test number** 998801444164**Result** ✓ Passed**MOT #13** 2014-05-21 14:19**MOT test number** 838201744197**Result** ✗ Failed**Fail** Driver's seat insecure (6.2.A.1)**Fail** Horn not working (1.6.2a)**MOT #12** 2013-03-09 13:26**MOT test number** 116318263427**Result** ✓ Passed**MOT #11** 2012-03-10 09:50**MOT test number** 165380372096**Result** ✓ Passed**Notice** Spare tyre defective**MOT #10** 2012-03-10 09:50**MOT test number** 848500972065**Result** ✗ Failed**Notice** Spare tyre defective**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #9** 2011-03-15 11:50**MOT test number** 186814571023**Result** ✓ Passed

**MOT #8** 2011-03-14 12:50**MOT test number** 545213971049**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #7** 2010-03-11 08:54**MOT test number** 134100870460**Result** ✓ Passed**Advice** Front constant velocity joint gaiter deteriorated (2.5.C.1a)**MOT #6** 2009-03-14 13:17**MOT test number** 252533879075**Result** ✓ Passed**MOT #5** 2008-03-08 09:55**MOT test number** 823598668061**Result** ✓ Passed**MOT #4** 2007-02-19 15:42**MOT test number** 101390457077**Result** ✓ Passed**MOT #3** 2006-10-04 11:16**MOT test number** 832867876221**Result** ✓ Passed



MOT #2	2006-09-29 08:01
MOT test number	823322276283
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2006-04-21 17:18
MOT test number	804281216196
Result	✓ Passed





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>WJ02BYU</b>
Plate since	2019-03-29
Current registration	<b>WJ02BYU</b>
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-04-17
Last registration	2021-04-12
Complete history	<a href="#">See info</a>



Registration #1	2002-04-17	14 mi
Registration #2	2006-04-21	17.398 mi
Registration #3	2006-09-29	18.768 mi
Registration #4	2006-10-04	18.768 mi
Registration #5	2007-02-19	19.446 mi
Registration #6	2008-03-08	22.458 mi
Registration #7	2009-03-14	25.199 mi
Registration #8	2010-03-11	27.753 mi
Registration #9	2011-03-14	31.294 mi
Registration #10	2011-03-15	31.294 mi
Registration #11	2012-03-10	33.911 mi
Registration #12	2013-03-09	36.693 mi
Registration #13	2014-05-21	38.829 mi
Registration #14	2015-05-20	39.377 mi
Registration #15	2016-05-20	39.377 mi
Registration #16	2017-05-20	39.377 mi
Registration #17	2018-05-20	39.377 mi
Registration #18	2019-05-20	39.377 mi
Registration #19	2020-05-20	39.377 mi
Registration #20	2021-05-20	39.377 mi
Registration #21	2022-05-20	39.377 mi
Registration #22	2023-05-20	39.377 mi
Registration #23	2024-05-20	39.377 mi
Registration #24	2025-05-20	39.377 mi
Registration #25	2026-05-20	39.377 mi
Registration #26	2027-05-20	39.377 mi

**More info** >



Safety ratings

NCAP rating ★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1595 mm
Height	1360 mm
Length	3718 mm
Wheel base	2385 mm
Kerb weight	805 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Single-Point Injection
Number of doors	5
Number of axles	2
Engine number	FP6J3657884