



report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Black
Year of manufacture	2009
Top speed	109 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	146 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 3

Date	2022-02-26
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2


Date	2022-02-12
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-10-15
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-02-13
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	19
Total items failed	7

MOT #20	2024-02-12 17:34
MOT test number	832700642349
Result	✓ Passed
Next expiry date	2025-02-13
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Coolant leak
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Central Rear upper stop lamp not working

**MOT #19**

2024-02-12 13:48

MOT test number

413367563903

Result**✗ Failed**

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Central Rear upper stop lamp not working

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Coolant leak

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #18

2023-02-03 15:36

MOT test number

714677762180

Result**✓ Passed****MOT #17**

2023-02-03 15:36

MOT test number

223492424277

Result**✗ Failed**

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #16

2022-02-14 14:34

MOT test number

821404589793

Result**✓ Passed**

**MOT #15** 2022-02-12 13:35**MOT test number** 288364340909**Result** ✗ Failed

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #14 2020-12-17 10:28**MOT test number** 253535364736**Result** ✓ Passed**MOT #13** 2019-12-10 13:07**MOT test number** 468044225562**Result** ✓ Passed**MOT #12** 2019-05-09 16:45**MOT test number** 271435529905**Result** ✓ Passed**MOT #11** 2018-05-02 13:31**MOT test number** 770344681943**Result** ✓ Passed**MOT #10** 2018-05-02 11:33**MOT test number** 501283641417**Result** ✗ Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #9** 2017-05-06 12:06**MOT test number** 549271546135**Result** ✓ Passed

Advice Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #8 2017-05-06 10:16**MOT test number** 362871354362**Result** ✗ Failed

Advice Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Fail Nearside Rear Stop lamp not working (1.2.1b)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

MOT #7 2016-05-06 13:10**MOT test number** 730008972967**Result** ✓ Passed**MOT #6** 2016-05-06 13:10**MOT test number** 867613710458**Result** ✗ Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #5 2015-05-08 11:14**MOT test number** 597788925101**Result** ✓ Passed

Advice Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #4 2014-05-06 16:51**MOT test number** 216796924118**Result** ✓ Passed



MOT #3	2014-05-06 12:02
MOT test number	265906224181
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2	2013-04-29 09:52
MOT test number	956189513102
Result	✓ Passed

MOT #1	2012-05-04 14:08
MOT test number	435935022188
Result	✓ Passed
Notice	O/s/f cv joint gaitor slight leak of grease from clip



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
13 February 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2009-06-24
Last registration	2024-02-12
Complete history	See info



Registration #1	2009-06-24	19 mi
Registration #2	2012-05-04	27.447 mi
Registration #3	2013-04-29	31.906 mi
Registration #4	2014-05-06	35.026 mi
Registration #5	2014-05-06	35.026 mi
Registration #6	2015-05-08	36.032 mi
Registration #7	2016-05-06	40.902 mi
Registration #8	2016-05-06	40.902 mi
Registration #9	2017-05-06	43.868 mi
Registration #10	2017-05-06	43.868 mi
Registration #11	2018-05-02	49.036 mi
Registration #12	2018-05-02	49.037 mi
Registration #13	2019-05-02	55.277 mi
Registration #14	2019-05-02	55.277 mi
Registration #15	2019-05-02	55.277 mi
Registration #16	2019-05-02	55.277 mi
Registration #17	2019-05-02	55.277 mi
Registration #18	2019-05-02	55.277 mi
Registration #19	2019-05-02	55.277 mi
Registration #20	2019-05-02	55.277 mi
Registration #21	2019-05-02	55.277 mi
Registration #22	2019-05-02	55.277 mi
Registration #23	2019-05-02	55.277 mi
Registration #24	2019-05-02	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9B76657