



LD57HT0

report date: 2024-03-29

General information

Make	MINI
Model	MINI (R57) COOPER
Colour	Silver
Year of manufacture	2007
Top speed	123 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-01-14
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-26
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	21
Total items failed	16

MOT #19	2024-04-16 15:30
MOT test number	548524148865
Result	✓ Passed
Next expiry date	2025-04-26

MOT #18	2024-04-02 10:54
MOT test number	411778136006
Result	✗ Failed
Fail	Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #17	2023-04-20 10:31
MOT test number	797170815423
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2022-04-27 11:03
MOT test number	852639566608
Result	✓ Passed

**MOT #15**

2021-02-16 12:36

MOT test number

344925662214

Result

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Coolant leak
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14

2021-02-16 09:23

MOT test number

961116059572

Result

✗ Failed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Coolant leak
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13

2020-01-31 11:45

MOT test number

485833633197

Result

✓ Passed

**MOT #12** 2020-01-31 08:49**MOT test number** 606425945205**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))**MOT #11** 2019-02-26 14:51**MOT test number** 736356805302**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Coolant leak**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2018-05-08 11:56**MOT test number** 251285551642**Result** ✓ Passed**MOT #9** 2017-05-05 09:41**MOT test number** 452095240405**Result** ✓ Passed**MOT #8** 2017-05-04 08:38**MOT test number** 704132142271**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #7** 2016-05-04 08:16**MOT test number** 483578664515**Result** ✓ Passed**MOT #6** 2015-04-27 11:55**MOT test number** 286187915100**Result** ✓ Passed**Notice** Front tyres worn on inner edges**MOT #5** 2013-11-12 12:56**MOT test number** 676016413316**Result** ✓ Passed**MOT #4** 2013-11-08 09:59**MOT test number** 849342413336**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)



MOT #3	2012-10-02 14:22
MOT test number	355306272445
Result	✓ Passed
Notice	Minor tyre wear to nearside rear inner and outer edges (3mm) and nearside front outer (3mm)

MOT #2	2011-09-27 10:52
MOT test number	459130571238
Result	✓ Passed

MOT #1	2010-09-27 17:04
MOT test number	780980070205
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
26 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	26 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-13
Last registration	2024-04-16
Complete history	See info



Registration #1	2007-09-13	19 mi
Registration #2	2010-09-27	21.091 mi
Registration #3	2011-09-27	23.552 mi
Registration #4	2012-10-02	26.561 mi
Registration #5	2013-11-08	29.809 mi
Registration #6	2013-11-12	29.810 mi
Registration #7	2015-04-27	41.361 mi
Registration #8	2016-05-04	48.466 mi
Registration #9	2017-05-04	58.526 mi
Registration #10	2017-05-05	58.527 mi
Registration #11	2018-05-08	60.313 mi
Registration #12	2019-05-08	60.313 mi
Registration #13	2019-05-08	60.313 mi
Registration #14	2019-05-08	60.313 mi
Registration #15	2019-05-08	60.313 mi
Registration #16	2019-05-08	60.313 mi
Registration #17	2019-05-08	60.313 mi
Registration #18	2019-05-08	60.313 mi
Registration #19	2019-05-08	60.313 mi
Registration #20	2019-05-08	60.313 mi
Registration #21	2019-05-08	60.313 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1140 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	B031H998
---------------	----------