



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-06
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-11-09
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	24
Total items failed	9

MOT #13	2020-11-10 12:35
MOT test number	119987252134
Result	✓ Passed
Next expiry date	2021-11-09
Advice	Exhaust has a minor leak of exhaust gases front exhaust (6.1.2 (a))
Advice	Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #12	2019-10-22 09:31
MOT test number	127333876518
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material both main (1.1.11 (c))

MOT #11	2018-10-05 10:53
MOT test number	255554448068
Result	✓ Passed
Advice	Exhaust mounting defective (6.1.2 (a))
Advice	Rear Tyre slightly damaged/cracking or perishing tyre edges feathering (5.2.3 (d) (ii))
Advice	Exhaust has a minor leak of exhaust gases middle/clamp deteriorated (6.1.2 (a))
Advice	Front Engine mounting damaged but not to excess deteriorated (6.1.8 (a) (i))
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #10**

2018-10-04 15:37

MOT test number

512868155113

Result**✗ Failed**

- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Exhaust has a minor leak of exhaust gases middle/clamp deteriorated (6.1.2 (a))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing tyre edges feathering (5.2.3 (d) (ii))
- MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Advice** Front Engine mounting damaged but not to excess deteriorated (6.1.8 (a) (i))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9

2017-10-10 10:11

MOT test number

117743353787

Result**✓ Passed**

- Advice** Offside hand brake effort bit low
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8

2016-10-14 14:42

MOT test number

782886778168

Result**✓ Passed**

- Advice** Offside Rear hand brake low effort
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #7** 2016-10-14 11:09**MOT test number** 104229428365**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside Rear hand brake low effort**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance lens missing (1.4.A.2e)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #6** 2015-10-06 12:08**MOT test number** 229236628600**Result** ✓ Passed**MOT #5** 2015-10-05 14:56**MOT test number** 447089492043**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases flexi (7.1.2)**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2014-07-30 10:33**MOT test number** 715481214276**Result** ✓ Passed



MOT #3	2013-10-08 15:29
MOT test number	628421083202
Result	✓ Passed

MOT #2	2012-10-10 11:11
MOT test number	706404482247
Result	✓ Passed
<div>Advice</div> Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2011-10-31 16:55
MOT test number	609454001368
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
30 June 2021

X

MOT

Expired:
9 November 2021

Tax status	Expired at 30 June 2021
Days left	1035 days too late
MOT expiry date	9 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DN58DLX
Plate since	2019-03-29
Current registration	 DN58DLX
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-12-24
Last registration	2020-11-10
Complete history	See info



Registration #1	2008-12-24	26 mi
Registration #2	2011-10-31	23.255 mi
Registration #3	2012-10-10	34.913 mi
Registration #4	2013-10-08	47.294 mi
Registration #5	2014-07-30	56.965 mi
Registration #6	2015-10-05	65.316 mi
Registration #7	2015-10-06	65.363 mi
Registration #8	2016-10-14	70.500 mi
Registration #9	2016-10-14	70.500 mi
Registration #10	2016-10-14	70.500 mi
Registration #11	2016-10-14	70.500 mi
Registration #12	2016-10-14	70.500 mi
Registration #13	2016-10-14	70.500 mi
Registration #14	2016-10-14	70.500 mi
Registration #15	2016-10-14	70.500 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564