





General information

| Make | HONDA |
|---------------------|---------------------|
| Model | HR-V I-DTEC SE NAVI |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 119 mph |
| 0 - 60 mph | 10.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 2.000 rpm |
| Engine capacity | 1.597 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 64.2 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 68.9 mpg |
| CO2 emission | 108 g/km |
| CO2 label | В |







| 2021-09-22 |
|-------------|
| 1 |
| View report |
| |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-09-14 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 8 |
| Total items failed | 2 |

| MOT #8 | 2023-09-04 10:42 |
|------------------|------------------|
| MOT test number | 726142844406 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-14 |

| MOT #7 | | 2022-09-15 12:32 |
|----------|--|------------------|
| MOT test | number | 284600013295 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| МОТ #6 | 2021-07-20 08:02 |
|-----------------|------------------|
| MOT test number | 532763236258 |
| Result | ✓ Passed |

| MOT #5 | 2020-07-24 14:37 |
|-----------------|------------------|
| MOT test number | 309502114377 |
| Result | ✓ Passed |





| MOT #4 | | 2020-07-24 14:37 |
|-------------------------|--|------------------|
| MOT test number | | 625887278117 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Rear Valve stem seriously damaged (5.2.3 (j)) | |
| | | |
| MOT #3 | | 2019-08-20 15:38 |
| MOT test number | | 638472630254 |
| Result | | ✓ Passed |
| | | |
| MOT #2 | | 2018-08-16 14:34 |
| MOT test number | | 656065934145 |
| Result | | ✓ Passed |

| Advice | Offside Front Tyre worn close to legal limit/worn on edge worn close wear bars 4.0 mm (5.2.3 (e)) |
|----------------|---|
| Advice (e)) | Nearside Front Tyre worn close to legal limit/worn on edge worn close to wear bars 3.0mm (5.2.3 |

| MOT #1 | 2018-08-16 09 | 9:54 |
|----------------|--|-------|
| MOT test | number 210104762 | 153 |
| Result | 🗙 Fa | ailed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge worn close wear bars 4.0 mm (5.2.3 (e | ē)) |
| Advice (e)) | Nearside Front Tyre worn close to legal limit/worn on edge worn close to wear bars 3.0mm (5.2. | .3 |
| | learside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on nearside rear outer shoulder (5.2.3 (d) (i)) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 October 2024 | ✓ MOT Expires: 14 September 2024 |
|--|---|
| Tax status | Valid until 1 October |
| Days left | 156 |
| MOT expiry date | 14 September 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| | E Store |
| Date | 1. E |
| Category | amt |
| Туре | |

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HONDA had different number plates | |
| Number of plates | |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-08-27 |
| Last registration | 2023-09-04 |
| Complete history | <u>See info</u> |



| Registration #1 | 2015-08-27 | 16 mi |
|------------------|------------|------------|
| Registration #2 | 2018-08-16 | 15.791 mi |
| Registration #3 | 2018-08-16 | 15.791 mi |
| Registration #4 | 2019-08-20 | 20.646 mi |
| Registration #5 | 2020-07-24 | 25.308 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|------------------------|
| Adult | 86% |
| Children | 79% |
| Pedestrian | 72% |
| Safety systems | 71% |
| Overall rating | 79% |
| Video | <u>see crash video</u> |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1772 mm |
| Height | 1605 mm |
| Length | 4294 mm |
| Wheel base | 2610 mm |
| Kerb weight | 1404 kg |
| Max. allowed weight | 1870 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 50 I |
| | 50 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |