





report date: 2024-03-29

## General information

Make	BMW
Model	123 123D M SPORT
Colour	Black
Year of manufacture	2010
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	201 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



AV60MVE report date: 2024-03-29

MOT history

MOT expiry date	2025-04-25
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	19
Total items failed	12

MOT #13		2024-04-25 17:57
MOT test	number	577626777875
Result		<b>✓</b> Passed
Next exp	ry date	2025-04-25
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Minor Offside Front Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))		
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #12		2024-0	4-25 17:57
MOT test	number	8605	98826967
Result			<b>×</b> Failed
Advice	Offside Front Sho	ock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Dire	ection indicator slightly discoloured (4.4.3 (a))	
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))			
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))			
Pass wit	th rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Minor	Offside Front Side	repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a)	(i))

CarCheck.co.uk page 3/13



Result

**AV60MVE** 

report date: 2024-03-29

× Failed

**MOT #11** 2023-04-26 14:47

MOT test number 989751213814

Advice Emission too clean to detect

MOT #10 2023-04-05 09:31

**MOT test number** 940000639805

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

MOT #9 2020-12-05 13:16

**MOT test number** 391309845336

**Result** ✓ Passed

MOT #8 2019-12-21 13:09

**MOT test number** 746391680873

Result 

Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #7 2018-12-15 12:35

**MOT test number** 294615527719

**Result** ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

× Failed

**MOT #6** 2018-12-14 15:51

**MOT test number** 400954861313

Result

Fail Nearside Front Suspension arm pin or bush excessively worn rear arm inner bush (5.3.4 (a) (i))

**Fail** Windscreen washer not working (3.5 (a))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Suspension arm ball joint likely to become detached front arm excessive movement (5.3.4 (a) (ii))

**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Horn not working (7.7 (a) (ii))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Fail** Offside Front Suspension arm ball joint likely to become detached front arm excessive movement (5.3.4 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #5** 2017-12-20 12:02

**MOT test number** 442416173648

Result \( \sqrt{Passed} \)

**Advice** Engine covers & under trays fitted

MOT #4 2016-12-20 12:24

MOT test number 241080920350

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3 2015-12-23 09:39

**MOT test number** 257372709196

**Result** ✓ Passed

Advice All four tyres are stretched but are seated

MOT #2 2014-12-12 11:14

MOT test number 455486944380

**MOT #1** 2013-12-17 13:07

**MOT test number** 517871953321

**Result** 
✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	25 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report \( \frac{1}{2} \)	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	NIE NIE
Plate since	200.00.00
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



AV60MVE report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-10-26
Last registration	2024-04-25
Complete history	See info



Registration #1	2010-10-26	14 mi
Registration #2	2013-12-17	22.144 mi
Registration #3	2014-12-12	31.481 mi
Registration #4	2015-12-23	38.422 mi
Registration #5	2016-12-20	39.658 mi
Registration #6	2017-12-20	62.751 mi
Registration #7	2018-12-14	76.439 mi
Registration #8	2018-12-15	76.450 mi
Registration #9		11.177 mi
Registration #10		11.117 es
Registration #11		11.117 es
Registration #12		11.777 es
Registration #13		11.177 es
Registration #14		11.777 es
Registration #15		11.177 ms

More info >

CarCheck.co.uk page 12/13



AV60MVE report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1748 mm
Height	1423 mm
Length	4360 mm
Wheel base	2660 mm
Kerb weight	1420 kg
Max. allowed weight	1860 kg

# Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2
Engine number 87517619