





General information

Make	MAZDA
Model	BT-50 4X4 TS2 DCB P/U
Colour	Silver
Year of manufacture	2007
Top speed	98 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	2.499 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	36.2 mpg
Consumption combined	31.7 mpg





Internet history

Entry	2
Date	

Pictures

2022-01-23

17

Listing price

View report




source: autotrader.co.uk

Entry 1	
Date	2021-12-26
Pictures	17
Listing price	View report



source: autotrader.co.uk









MOT history

MOT expiry date	2025-04-11
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	56
Total items failed	10

MOT #20		2024-04-12 11:33
MOT test	number	244455823007
Result		🗸 Passed
Next expi	ry date	2025-04-11
Advice Nearside Front Steering box has slight free play detected at steering wheel (2.3 (a) (i))		
Advice	Rear Brake pipe corroded, covered in grease or other material all greased (1.1.1	1 (c))

MOT #19		2024-04-12 07:26
MOT test number		256378629145
Result		× Failed
MAJOR Offside Rear Servic	e brake excessively binding (1.2.1 (f))	
DANGEROUS Parking brak	e efficiency less than 50% of the requi	red value (1.4.2 (a) (ii))
MAJOR Nearside Rear Inner Suspension component mounting prescribed area excessively damaged significantly reducing structural strength sill (5.3.6 (a) (i))		
MAJOR Offside Rear Parkin	g brake inoperative on one side (1.4.1	(a))
Advice Rear Brake pipe co	rroded, covered in grease or other mat	erial all greased (1.1.11 (c))
Advice Nearside Front Stee	ering box has slight free play detected	at steering wheel (2.3 (a) (i))
MAJOR Nearside Rear Park	ing brake inoperative on one side (1.4.	1 (a))





MOT #18	2023-02-22 09:47
MOT test number	602648755012
Result	✓ Passed
Advice Rear Brakes imbalanced requirements only just met. It would appear that th requires adjustment or repair. 32% (1.2.1 (b) (i))	e braking system
Advice Offside Front body mount area corroded	
Minor Headlamp lens slightly defective both (4.1.1 (b) (i))	
Advice Brake load sensing valve stiff (1.1.17 (c) (ii))	
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.1	11 (c))
Advice Steering linkage ball joint has slight play pittman arm (2.1.3 (b) (i))	
Advice Front radiator support corroded/ holed	

MOT #17	2022-01-21 18:08
MOT test number	945374701631
Result	✓ Passed

MOT #16	2021-03-04 17:12
MOT test number	510885620102
Result	✓ Passed
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 ((c))

MOT #15		2020-03-07 12:20
MOT test	number	780678219253
Result		✓ Passed
Advice	Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	





MOT #14		2020-03-07 12:20
MOT test number		764897103539
Result		🗙 Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Set	rvice brake binding but not excessively (1.2.1 (f))	
Advice Offside Front Low	wer Shock absorbers has a slightly worn bush (5.3.2 (c))	
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Front S	Service brake binding but not excessively (1.2.1 (f))	
Advice Nearside Front L	ower Shock absorbers has a slightly worn bush (5.3.2 (c))	

MOT #13	2019-03-01 09:05
MOT test number	726938779677
Result	✓ Passed

MOT #12	2019-02-27 18:24
MOT test number	694266727722
Result	🗙 Failed
MAJOR Exhaust has a major leak of exhaust gases (6.1.2 (a))DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #11	2018-03-14 14:19
MOT test number	482890677030
Result	✓ Passed





MOT #	10	2018-03-13 15:48
MOT te	st number	740233522813
Result		🗙 Failed
Fail	Brake pipe excessively corroded front to rear at front (3.6.B.2c)	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Offside front brake excessively fluctuating (3.7.B.3)	
Fail	Nearside Front Brake pipe excessively corroded (3.6.B.2c)	
Fail	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advid	e Brake pipe slightly corroded all 3 comp valve pipes (3.6.B.2c)	
Fail	Offside Front Brake pipe excessively corroded (3.6.B.2c)	

MOT #9		2017-12-13 09:33
MOT test	number	997382860918
Result		✓ Passed
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Front Tyre worn close to the legal limit 1.8mm (4.1.E.1)	
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear wheel bearing has slight play (2.6.2)	
Advice	Nearside Rear Tyre worn close to the legal limit 2.3mm (4.1.E.1)	





MOT #8		2016-12-29 11:44	
MOT test	number	633102439456	
Result		✓ Passed	
Advice	Exhaust has a minor leak of exhaust gases centre joint (7.1.2)		
MOT #7		2015-12-08 14:29	
MOT test	number	594475638951	
Result		Passed	
Advice	Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Advice Offside Rear Brake pipe slightly corroded The break pipe to the compensator is corroded (3.6.B.2c)		or is corroded	
Advice	Advice Centre Rear Brake pipe slightly corroded The break pipe to the break tree is corroded (3.6.B.2c)		
Advice (3.6.B.2c)	Offside Rear Brake pipe slightly corroded The main metal break pipe to the	rear is corroded	
Advice	Centre Rear Brake pipe slightly corroded The rear pipe to the break tree is o	corroded (3.6.B.2c)	

МОТ #6	2014-12-31 10:31
MOT test number	605745264313
Result	✓ Passed

MOT #5	2013-12-19 11:20
MOT test number	878513553397
Result	✓ Passed
Advice Brake pipe slightly corroded (3.6.B.2c)	





MOT #4		2012-12-17 16:51
MOT test	number	685102152389
Result		✓ Passed
Advice	Centre Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Centre Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Centre Rear Brake pipe slightly corroded (3.6.B.2c)	

MOT #3		2012-12-17 12:48
MOT test	number	847562952356
Result		🗙 Failed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Centre Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Centre Rear Brake pipe slightly corroded (3.6.B.2c)	
Fail Centre Rear Drive shaft uj which forms part of the suspension has excessive play in a universal joint (2.4.G.4b)		
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Centre Brake pipe slightly corroded (3.6.B.2c)	

MOT #2	2011-12-19 11:48
MOT test number	157693851375
Result	✓ Passed





MOT #1	2010-12-16 10:03
MOT test number	391440450387
Result	✓ Passed



NV57ZGC report date: 2024-03-28

Tax & MOT check

X Untaxed	√ MOT
Tax expired: 31 October 2023	Expires: 11 April 2025
Tax status	Expired at 31 October 2023
Days left	180 days too late
MOT expiry date	11 April 2025
Full MOT history	See MOT history





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPLI
Damaye 2	E E E E
Date	*
Category	AMP
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-12-29
Last registration	2024-04-12
Complete history	<u>See info</u>



Registration #1	2007-12-29	9 mi
Registration #2	2010-12-16	27.791 mi
Registration #3	2011-12-19	36.171 mi
Registration #4	2012-12-17	42.719 mi
Registration #5	2012-12-17	42.719 mi
Registration #6	2013-12-19	48.901 mi
Registration #7	2014-12-31	55.358 mi
Registration #8	2015-12-08	60.752 mi
Registration #9	2016-12-29	69.634 mi
Registration #10	2017-12-13	77.264 mi
Registration #11	2018-03-13	78.570 mi
Registration #12	2018-03-14	78.570 mi
Registration #13		
Registration #15		
Registration #14		11.227 44
-		0.202 es
Registration #14		0.000 est 0.000 est 0.000 est
Registration #14 Registration #15		0.000 est 0.000 est 0.000 est 0.000 est
Registration #14 Registration #15 Registration #16		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #14 Registration #15 Registration #16 Registration #17		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11, 227 46 11, 227 46
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11, 227 46 11, 227 46

More info >





Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	WLAT 737203