




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO R LINE TDI BLUEMOTION TECHNOLO
Colour	Blue
Year of manufacture	2016
Top speed	134 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	320 Nm at 3.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-12-04
Pictures	1



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-27
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #8 2024-01-23 15:32

MOT test number 823406828469

Result ✓ Passed

Next expiry date 2025-01-27

- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both rear bushes (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

MOT #7 2023-01-16 14:39

MOT test number 724620116654

Result ✓ Passed

- Advice** Offside Front Tyre slightly damaged Outer sidewall (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged Outer sidewall (5.2.3 (d) (ii))
- Advice** Nearside Front DRL not working
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #6	2022-01-07 16:15
MOT test number	882601014446
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5	2021-01-26 16:07
MOT test number	314723923989
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rear discs (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Brake disc worn, but not excessively Both front discs (1.1.14 (a) (i))
Advice	Nearside Front Tyre slightly damaged outer side wall (5.2.3 (d) (ii))

MOT #4	2021-01-26 11:51
MOT test number	823631880386
Result	✗ Failed
Advice	Brake disc worn, but not excessively Both front discs (1.1.14 (a) (i))
Fail	Offside Front Suspension arm pin or bush excessively worn alloy bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre slightly damaged outer side wall (5.2.3 (d) (ii))
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rear discs (1.1.14 (a) (ii))
Fail	Nearside Front Suspension arm pin or bush excessively worn alloy bush (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3	2020-01-28 13:54
MOT test number	741421146035
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2020-01-28 09:40
MOT test number	246636531338
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2019-03-15 16:10
MOT test number	183440407812
Result	✓ Passed
Advice	Nearside Rear Tyre stepping on inner



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
27 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	27 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-04-08
Last registration	2024-01-23
Complete history	See info



Registration #1	2016-04-08	23 mi
Registration #2	2019-03-15	46.639 mi
Registration #3	2020-01-28	52.834 mi
Registration #4	2020-01-28	52.834 mi
Registration #5	2021-01-26	67.744 mi
Registration #6	2022-01-26	75.277 mi
Registration #7	2022-01-26	75.277 mi
Registration #8	2022-01-26	75.277 mi
Registration #9	2022-01-26	75.277 mi
Registration #10	2024-01-23	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2080 mm
Height	1406 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1275 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of axles	2

Engine number

B147270