



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Grey
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.900 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-11
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-30
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	32
Total items failed	5

MOT #13	2023-07-15 08:44
MOT test number	763111011038
Result	✓ Passed
Next expiry date	2024-07-30
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12	2022-07-29 12:37
MOT test number	597155154158
Result	✓ Passed

MOT #11	2022-07-22 10:50
MOT test number	652445619303
Result	✗ Failed
Fail	Offside Side repeater not working (4.4.1 (a) (ii))

MOT #10	2021-07-31 10:14
MOT test number	845930870857
Result	✓ Passed

**MOT #9** 2021-06-17 15:41**MOT test number** 376014428784**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Direction indicator slightly discoloured both sides (4.4.3 (a))**Advice** Play in steering rack inner joint(s)**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #8** 2020-06-18 13:50**MOT test number** 650281500898**Result** ✓ Passed**Advice** Shock absorbers has a slightly worn bush both rear (5.3.2 (c))**Advice** Play in steering rack inner joint(s)**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cut to sidewall (5.2.3 (d) (ii))

**MOT #7** 2019-05-01 10:48**MOT test number** 710151134012**Result** ✓ Passed

- Advice** Squeak from steering
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Nail in tyre
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2019-04-30 08:48**MOT test number** 612046491843**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Squeak from steering
- Fail** Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Nail in tyre

**MOT #5** 2018-05-23 08:34**MOT test number** 935210265225**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-05-23 08:22**MOT test number** 344451894361**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #3** 2017-05-04 09:06**MOT test number** 994667812682**Result** ✓ Passed**MOT #2** 2016-09-03 09:29**MOT test number** 608308886504**Result** ✓ Passed



MOT #1	2015-09-17 09:50
MOT test number	509442455228
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit 2.14mm remaining (4.1.E.1)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Covers fitted to underside of vehicle



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 July 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	30 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	RO62XTW
Plate since	2019-09-29
Current registration	RO62XTW
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-26
Last registration	2023-07-15
Complete history	See info



Registration #1	2012-09-26	24 mi
Registration #2	2015-09-17	41.092 mi
Registration #3	2016-09-03	56.058 mi
Registration #4	2017-05-04	63.064 mi
Registration #5	2018-05-23	75.372 mi
Registration #6	2018-05-23	75.372 mi
Registration #7	2019-04-30	88.471 mi
Registration #8	2019-05-01	88.471 mi
Registration #9	2019-05-01	88.471 mi
Registration #10	2019-05-01	88.471 mi
Registration #11	2019-05-01	88.471 mi
Registration #12	2019-05-01	88.471 mi
Registration #13	2019-05-01	88.471 mi
Registration #14	2019-05-01	88.471 mi
Registration #15	2019-05-01	88.471 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D4HBBU548086
---------------	--------------