





report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC
Colour	White
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	11.5 seconds
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 104 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date	2021-01-29	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



SF13RWV
report date: 2024-03-29

MOT history

MOT expiry date	2024-11-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	27
Total items failed	3

MOT #12	2023-11-13 16:09
MOT test number	149558895095
Result	✓ Passed
Next expiry date	2024-11-12
Advice UNDER TRAYS FITTED	

MOT #11		2023-11-13 11:03
MOT test	number	277388212710
Result		X Failed
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	1 (a) (ii))
Fail No	earside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	UNDER TRAYS FITTED	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10

MOT test number

Result

Advice Under trays fitted

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

MOT test number

745520486054

Result

Advice Under trays fitted

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #8		2021-09-09 08:48
MOT test	number	941371775862
Result		✓ Passed
Advice (ii))	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	Inner face (1.1.14 (a)
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii))		ed Inner face (1.1.14 (a)
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Clutch pedal rubber missing	
Advice Perished a	Nearside Front Tyre worn close to legal limit/worn on edge 2.01mm to 0.00 nd cracked (5.2.3 (e))	mm on inside edge -

CarCheck.co.uk page 4/13



(ii))

SF13RWV

report date: 2024-03-29

MOT #7 2021-09-09 08:48 185534991203 **MOT** test number Result × Failed **Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.01mm to 0.00mm on inside edge -Perished and cracked (5.2.3 (e)) Advice Clutch pedal rubber missing **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a) (ii)) **Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e)) **Pass with rectification** Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner face (1.1.14 (a)

MOT #6	2020-08-27 10:30
MOT test number	925047116663
Result	✓ Passed
Advice Note: Heatshield/sound proofing loose.	

Advice Note: Heatshield/sound proofing loose.	
MOT #5	2019-07-31 10:35
MOT test number	327515691807
Result	✓ Passed
MOT #4	2018-08-16 10:03
MOT test number	563429696820
Result	✓ Passed
MOT #3	2018-01-13 12:07
MOT test number	402637390408
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2		2017-01-07 10:50
MOT test	number	833534854296
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit Inner and outer edge (4.1.E.1)	
Advice	Under trays fitted	
Advice	Nearside Front Tyre worn close to the legal limit Inner and outer edge (4.1.E.1)	
Advice	Engine covers fitted	

MOT #1	2016-01-20 09:46
MOT test number	735788542609
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	history
OWITEL	HISLULY

e when mistery	
For how long did the current and previous owner(s) have this FORD? How many owners defect it in the premium report and see all owner registrations. Download the full report be	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	OK SIE
Flate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-21
Last registration	2023-11-13
Complete history	See info



Registration #1	2013-03-21	18 mi
Registration #2	2016-01-20	24.217 mi
Registration #3	2017-01-07	27.538 mi
Registration #4	2018-01-13	29.747 mi
Registration #5	2018-08-16	31.398 mi
Registration #6	2019-07-31	39.016 mi
Registration #7	2020-08-27	48.015 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1626 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1274 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
r der denvery	Plate Forme injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 13/1