



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO 2900 L1H1 CDTi P/V SPORTIVE
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-06-11
Pictures	99
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-05-15
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	15
Total items failed	4

MOT #8	2023-05-16 10:04
MOT test number	662548486656
Result	✓ Passed
Next expiry date	2024-05-15

MOT #7	2023-05-15 12:20
MOT test number	971507842001
Result	✗ Failed
<div><div>Fail</div> Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))</div>	
<div><div>Advice</div> Front Brake pad(s) wearing thin (1.1.13 (a) (ii))</div>	
<div><div>Advice</div> Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	
<div><div>Fail</div> Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))</div>	
<div><div>Advice</div> Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))</div>	
<div><div>Advice</div> Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	

**MOT #6** 2022-05-09 09:32**MOT test number** 101064440509**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))**Advice** Nearside Tyre worn close to legal limit/worn on edge front and rear (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin o/s and n/s (1.1.13 (a) (ii))**MOT #5** 2021-05-13 15:44**MOT test number** 955066195440**Result** ✓ Passed**MOT #4** 2021-05-10 16:24**MOT test number** 107447615319**Result** ✗ Failed**Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #3** 2020-09-08 16:24**MOT test number** 999304694276**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #2** 2020-09-08 10:11**MOT test number** 942033338577**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2019-08-29 10:57**MOT test number** 402374478081**Result** ✓ Passed**Advice** Brake pad(s) wearing thin Front brake pads appear worn. (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✓  
**MOT**

**Expires:**  
15 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	15 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>FN66LVS</b>
Plate since	2019-06-29
Current registration	<b>FN66LVS</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-14
Last registration	2023-05-16
Complete history	<a href="#">See info</a>



Registration #1	2016-09-14	23 mi
Registration #2	2019-08-29	32.749 mi
Registration #3	2020-09-08	38.784 mi
Registration #4	2020-09-08	38.784 mi
Registration #5	2021-05-10	39.016 mi
Registration #6	2022-05-20	39.277 mi
Registration #7	2022-05-20	39.277 mi
Registration #8	2022-05-20	39.277 mi
Registration #9	2022-05-20	39.277 mi
Registration #10	2023-05-16	39.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4998 mm
Kerb weight	1680 kg
Max. allowed weight	2920 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MB - C109283LWU