





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TSI
Colour	Silver
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	251 Nm at 1.500 rpm
Engine capacity	1.790 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg
CO2 emission	178 g/km
CO2 label	1



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-07

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-15
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	19
Total items failed	0

MOT #13	2023-08-16 12:29
MOT test number	482420646468
Result	✓ Passed
Next expiry date	2024-08-15

M	OT #12		2023-08-15 09:12
M	OT test	number	437691198534
R	esult		X Failed
	MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
	MAJOR	Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
	MAJOR	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
	Minor i))	Offside Registration plate lamp inoperative in the case of multiple lamps or light s	sources (4.7.1 (b)

MOT #11		2022-09-21 15:55
MOT test	number	651407976638
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	1.14 (a) (ii))
Advice	Offside Rear Nail in tyre	
Advice	Tpms light on	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT test number

887253872714

Result

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front suspension arm rear bushes (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #8

MOT test number

872874144609

Result

Advice

Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

MOT #7

MOT test number

Result

Advice

Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

Advice

Rear tyres starting to wear unevenly on inner edge

MOT #6

MOT test number

155149155080

Result

Advice Front tyres getting worn

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5	2016-09-27 07:49
MOT test number	627128106702
Result	✓ Passed
MOT #4	2015-09-02 07:48
MOT test number	449456480444
Result	✓ Passed
MOT #3	2014-10-01 15:36
MOT test number	487054274298
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2013-09-17 08:51
MOT test number	878790263239
Result	✓ Passed
Notice Front tyres getting worn	

MOT #1	2012-09-18 08:50
MOT test number	276662562228
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



-

PE59CLN

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.

mn.n.n

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-28
Last registration	2023-08-16
Complete history	See info



Registration #1	2009-09-28	29 mi
Registration #2	2012-09-18	12.644 mi
Registration #3	2013-09-17	15.918 mi
Registration #4	2014-10-01	19.674 mi
Registration #5	2015-09-02	22.810 mi
Registration #6	2016-09-27	26.150 mi
Registration #7	2017-09-22	30.373 mi
Registration #8	2018-09-27	39.786 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

CarCheck.co.uk page 12/12