



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B200 SE
Colour	Blue
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	2.035 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 3

Date	2023-01-01
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-10-02
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-30
Pictures	37
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-30
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	12
Total items failed	5

MOT #16 2023-09-16 09:54**MOT test number** 344659664108**Result** ✓ Passed**Next expiry date** 2024-09-30**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #15** 2023-09-16 08:13**MOT test number** 440726684717**Result** ✗ Failed**Fail** Nearside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))**Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14** 2022-09-17 11:00**MOT test number** 557250496946**Result** ✓ Passed

**MOT #13** 2021-10-01 08:09**MOT test number** 908896580236**Result** ✓ Passed**MOT #12** 2020-08-26 10:05**MOT test number** 105179964668**Result** ✓ Passed**MOT #11** 2019-08-15 15:54**MOT test number** 196236819056**Result** ✓ Passed**MOT #10** 2018-08-21 15:41**MOT test number** 732106241787**Result** ✓ Passed**Advice** Rear All direction indicators slightly discoloured ns/os (4.4.3 (a))**MOT #9** 2018-08-21 10:48**MOT test number** 547749573227**Result** ✗ Failed**Advice** Rear All direction indicators slightly discoloured ns/os (4.4.3 (a))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2017-08-24 11:31**MOT test number** 646376228110**Result** ✓ Passed

**MOT #7** 2016-08-24 13:28**MOT test number** 133042654121**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-08-11 16:46**MOT test number** 618893425231**Result** ✓ Passed**Advice** Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #5** 2014-08-29 17:06**MOT test number** 456551544292**Result** ✓ Passed**MOT #4** 2013-08-06 13:07**MOT test number** 305128213227**Result** ✓ Passed**MOT #3** 2012-08-22 10:44**MOT test number** 945325332279**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Nail in offside rear tyre**MOT #2** 2011-08-23 13:10**MOT test number** 966415231298**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #1	2010-08-24 10:08
MOT test number	152036130283
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
30 September 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	30 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-01
Last registration	2023-09-16
Complete history	See info



Registration #1	2007-09-01	14 mi
Registration #2	2010-08-24	13.522 mi
Registration #3	2011-08-23	15.351 mi
Registration #4	2012-08-22	17.477 mi
Registration #5	2013-08-06	18.773 mi
Registration #6	2014-08-29	20.331 mi
Registration #7	2015-08-11	23.030 mi
Registration #8	2016-08-24	26.439 mi
Registration #9	2017-08-24	29.790 mi
Registration #10	2018-08-21	32.117 mi
Registration #11	2019-08-21	35.526 mi
Registration #12	2020-08-21	38.935 mi
Registration #13	2021-08-21	42.344 mi
Registration #14	2022-08-21	45.753 mi
Registration #15	2023-08-21	49.162 mi
Registration #16	2024-08-21	52.571 mi
Registration #17	2025-08-21	55.980 mi
Registration #18	2026-08-21	59.389 mi
Registration #19	2027-08-21	62.798 mi
Registration #20	2028-08-21	66.207 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1345 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26696030341979