



report date: 2024-03-29

General information

Make	KIA
Model	CARENS 2 CRDI
Colour	Silver
Year of manufacture	2014
Top speed	116 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2025-03-14
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	14
Total items failed	9

MOT #10 2024-03-08 09:49

MOT test number 404653172695

Result ✓ Passed

Next expiry date 2025-03-14

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2023-03-15 09:46

MOT test number 131788515717

Result ✓ Passed

MOT #8 2021-10-25 09:59

MOT test number 389717662368

Result ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2020-11-03 10:46**MOT test number** 599007447575**Result** ✓ Passed**Advice** Tyre pressure monitoring system stays on**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #6** 2020-11-03 10:46**MOT test number** 858875681756**Result** ✗ Failed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Tyre pressure monitoring system stays on**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2019-10-02 12:11**MOT test number** 483333946184**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #4** 2019-10-02 08:52**MOT test number** 570952999371**Result** ✗ Failed

Fail Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #3 2018-09-27 13:43**MOT test number** 300619465408**Result** ✓ Passed**MOT #2** 2018-09-21 10:37**MOT test number** 752720339473**Result** ✗ Failed

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #1 2017-07-14 13:45**MOT test number** 323411898311**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
14 March 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	MC14DXD
Plate since	2024-03-29
Current registration	MC14DXD
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-08-11
Last registration	2024-03-08
Complete history	See info



Registration #1	2014-08-11	28 mi
Registration #2	2017-07-14	36.907 mi
Registration #3	2018-09-21	42.792 mi
Registration #4	2018-09-27	42.792 mi
Registration #5	2019-10-02	49.653 mi
Registration #6	2019-10-02	49.653 mi
Registration #7	2019-10-02	49.653 mi
Registration #8	2019-10-02	49.653 mi
Registration #9	2019-10-02	49.653 mi
Registration #10	2019-10-02	49.653 mi
Registration #11	2019-10-02	49.653 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	76%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1805 mm
Height	1605 mm
Length	4525 mm
Wheel base	2750 mm
Kerb weight	1724 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4FDEH525323