

Ford



General information

Make	FORD
Model	KUGA TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	Н





MOT history

MOT expiry date	2025-02-28
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	18
Total items failed	9

MOT #14	2024-02-29 16:47
MOT test number	286867044681
Result	✓ Passed
Next expiry date	2025-02-28

MOT #13	2023-12-11 13:50
MOT test number	494617984789
Result	🗙 Failed
Fail Nearside Side repeater missing (4.4.1 (a) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Suspension arm pin or bush worn but not resulting in excessive movemer arm bushes (5.3.4 (a) (i))	nt both side trailing
Advice Play in steering rack inner joint(s)	
Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))	
FailWindscreen washer not working (3.5 (a))	
Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
FailNearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Rear exhaust heat shield insecure	
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	



MOT #12	2022-11-16 15:52
MOT test number	415316995144
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice Rear Tyre slightly damaged/cracking or perishing Both & worn on edge	s (5.2.3 (d) (ii))
Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #11		2021-06-28 14:41
MOT test i	number	343798559391
Result		✓ Passed
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive mo	ovement (5.3.4
Advice	Nearside Rear Tyre worn inner edge	
Advice	Front Registration plate deteriorated but not likely to be misread $(0.1 (b))$	
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excessive mov	rement (5.3.4 (a)
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2020-01-16 14:35
MOT test number	208693730174
Result	✓ Passed
МОТ #9	2019-01-07 13:37
MOT test number	108517855275
Result	✓ Passed

МОТ #8	2018-01-03 13:44
MOT test number	642244501815
Result	✓ Passed





MOT #7	2017-01-25 14:16	
MOT test number	245011673458	
Result	✓ Passed	
MOT #6	2016-07-15 15:22	
MOT test number	495940857913	
Result	✓ Passed	
MOT #5	2016-07-15 15:22	
MOT test number	561546397682	
Result	× Failed	
Pass with rectification position lamps (1.1.C.1a)	Nearside Registration plate lamp does not illuminate simultaneously with the	
Pass with rectification position lamps (1.1.C.1a)	Offside Registration plate lamp does not illuminate simultaneously with the	

MOT #4	2015-02-02 15:53
MOT test number	305193835074
Result	✓ Passed
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.	.li)

МОТ #3	2015-01-30 16:40
MOT test number	989210035007
Result	× Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
FailRear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Notice Items removed from driver's view prior to test	
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	





MOT #2	2014-01-13 14:55
MOT test number	378903914093
Result	✓ Passed
MOT #1	2013-01-14 15:35
MOT test number	178334613422
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 April 2025	Expires: 28 February 2025
Tax status	Valid until 1 April
Days left	336
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
formed methods	
Carrient registration	
Plate since	
Farle since Earnest registration	
Farle since Farle since Farle since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



EN59HDC report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-01-19
Last registration	2024-02-29
Complete history	<u>See info</u>



Registration #1	2010-01-19	17 mi
Registration #2	2013-01-14	30.178 mi
Registration #3	2014-01-13	40.543 mi
Registration #4	2015-01-30	64.232 mi
Registration #5	2015-02-02	64.411 mi
Registration #6	2016-07-15	98.641 mi
Registration #7	2016-07-15	98.641 mi
Registration #8		10.200 au
Registration #8 Registration #9		11.777 es
		01,000 est 01,000 est 01,000 est
Registration #9		11.777 46 11.777 46 11.777 46 11.777 46
Registration #9 Registration #10		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #9 Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1842 mm
Height	1677 mm
Length	4443 mm
Kerb weight	1613 kg
Max. allowed weight	2130 kg
Additional information	
Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

AS88158