



report date: 2024-03-28

General information

Make	JAGUAR
Model	XK8 XKR
Colour	Black
Year of manufacture	1999
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	370 BHP
Max. torque	525 Nm at 3.600 rpm
Engine capacity	3.996 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.1 mpg
Consumption extra urban	28.8 mpg
Consumption combined	22.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-17
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-05
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	30
Total items failed	8

MOT #21	2024-02-06 14:49
MOT test number	278580381196
Result	✓ Passed
Next expiry date	2025-02-05

MOT #20	2023-01-19 11:37
MOT test number	739337323464
Result	✓ Passed
Advice	All direction indicators slightly discoloured (4.4.3 (a))

MOT #19	2022-04-27 11:23
MOT test number	241283832892
Result	✓ Passed

**MOT #18**

2021-04-12 09:39

MOT test number

142106066497

Result

✓ Passed

Advice

Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

Advice

Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice

Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

MOT #17

2020-04-13 11:25

MOT test number

840832601565

Result

✓ Passed

MOT #16

2015-11-02 12:41

MOT test number

264253356619

Result

✓ Passed

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #15

2014-10-11 09:38

MOT test number

787504584222

Result

✓ Passed

MOT #14

2013-09-11 10:47

MOT test number

118184053263

Result

✓ Passed



MOT #13	2012-09-18 12:47
MOT test number	205542962221
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #12	2012-09-14 14:45
MOT test number	959098952222
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear position lamp(s) not working (1.1.A.3b)
Fail	Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)

MOT #11	2011-09-23 07:43
MOT test number	526056061256
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	F/floors rusty
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
Advice	Offside Rear Drive shaft uj which forms part of the suspension has slight play in a universal joint (2.4.G.4b)
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
Advice	Nearside Rear Drive shaft uj which forms part of the suspension has slight play in a universal joint (2.4.G.4b)

**MOT #10**

2011-09-21 11:09

MOT test number

386044261259

Result**✗ Failed**

- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Nearside Rear Drive shaft uj which forms part of the suspension has slight play in a universal joint (2.4.G.4b)
- Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Notice** F/floors rusty
- Advice** Offside Rear Drive shaft uj which forms part of the suspension has slight play in a universal joint (2.4.G.4b)
- Fail** Offside Front Lower Shock absorber has an excessively worn bush (2.7.4)

MOT #9

2010-09-23 16:06

MOT test number

773946160203

Result**✓ Passed**

- Notice** Nearside rear chassis leg is excessively corroded and close to failure, offside front floor pan corroded, nearside front lower ball joint worn

MOT #8

2010-09-23 08:52

MOT test number

311856560403

Result**✗ Failed**

- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Notice** Nearside rear chassis leg is excessively corroded and close to failure, offside front floor pan corroded, nearside front lower ball joint worn

MOT #7

2009-09-16 13:14

MOT test number

711489759201

Result**✓ Passed**
page 6/13

**MOT #6** 2009-09-14 13:17**MOT test number** 310437859451**Result** ✗ Failed**Fail** Driver's seat insecure (6.2.A.1)**Notice** Near side front and off side front of floor is blistered, slight play off side of rack, near side rear of chassis is blistered**MOT #5** 2008-09-10 11:47**MOT test number** 382294758279**Result** ✓ Passed**Notice** Near side rear wheel rim damaged**MOT #4** 2007-09-10 15:22**MOT test number** 310753357224**Result** ✓ Passed**MOT #3** 2006-09-16 12:37**MOT test number** 914409956205**Result** ✓ Passed**MOT #2** 2005-04-26 08:46**MOT test number** 963076415175**Result** ✓ Passed**MOT #1** 2005-04-25 12:53**MOT test number** 194075415136**Result** ✗ Failed**Fail** Nearside Front Upper Suspension arm has excessive play in a pin/bush (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
5 February 2025

Tax status	Valid until 1 March
-------------------	---------------------

Days left	307
------------------	-----

MOT expiry date	5 February 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	1999-12-31
Last registration	2024-02-06
Complete history	See info



Registration #1	1999-12-31	14 mi
Registration #2	2005-04-25	81.919 mi
Registration #3	2005-04-26	81.919 mi
Registration #4	2006-09-16	90.985 mi
Registration #5	2007-09-10	97.073 mi
Registration #6	2008-09-10	101.603 mi
Registration #7	2009-09-14	104.875 mi
Registration #8	2009-09-16	104.876 mi
Registration #9	2010-09-23	108.419 mi
Registration #10	2010-09-23	108.419 mi
Registration #11	2011-09-21	111.789 mi
Registration #12	2011-09-23	111.789 mi
Registration #13	2012-09-21	115.159 mi
Registration #14	2012-09-23	115.159 mi
Registration #15	2013-09-21	118.529 mi
Registration #16	2013-09-23	118.529 mi
Registration #17	2014-09-21	121.899 mi
Registration #18	2014-09-23	121.899 mi
Registration #19	2015-09-21	125.269 mi
Registration #20	2015-09-23	125.269 mi
Registration #21	2016-09-21	128.639 mi
Registration #22	2016-09-23	128.639 mi
Registration #23	2024-02-06	132.009 mi

More info >



Dimensions & weight

Width	2015 mm
Height	1306 mm
Length	4760 mm

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	EC9901141833