





General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI DSG DPF 140
Colour	Grey
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1

Date

2021-08-29

6


Pictures

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-12
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #14	2023-05-13 09:09
MOT test	number 589547483975
Result	✓ Passed
Next exp	iry date 2024-05-12
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13		2022-04-22 15:56
MOT test	number	637753138278
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2021-04-14 18:48
MOT test number	503592073974
Result	✓ Passed
Advice Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))	





MOT #11	2020-04-23 15:08
MOT test number	206521607720
Result	✓ Passed
MOT #10	2019-04-13 10:05
MOT test number	191832691488

F	lesult		✓ Passed
	Minor	Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
	Minor	Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #9		2018-04-18 12:13
MOT test	number	759304345181
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #8	2017-04-20 15:23
MOT test number	560130838608
Result	✓ Passed
MOT #7	2016-04-26 12:06

MOT test number	798810169645
Result	✓ Passed

MOT #6	2015-04-24 12:11
MOT test number	539534615140
Result	✓ Passed





MOT #5	2015-04-23 14:18
MOT test number	847043215112
Result	🗙 Failed
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structur	e (4.1.D.1b)
Pass with rectification Offside Headlamp aim too low (1.8)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectificationNearside Headlamp aim too low (1.8)	
МОТ #4	2014-04-15 12:51
MOT test number	285655204414

MOT #3	2013-03-04 10:24
MOT test number	706543763047
Result	✓ Passed

MOT #2	2011-11-01 12:24
MOT test number	445285401418
Result	✓ Passed

MOT #1		2011-11-01 12:24
MOT test number		675445801372
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too low (1.8)	
Pass with rectification	Nearside Headlamp aim too low (1.8)	

🗸 Passed



Tax & MOT check

Tax calculation

√ Taxed	√ МОТ
Tax due: 1 September 2024	Expires: 12 May 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	12 May 2024
Full MOT history	See MOT history

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY ANY ANY ANY ANY ANY ANY ANY ANY ANY AN	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In kilometers
Mileage registrations	15
First mileage registration	2008-11-27
Last registration	2023-05-13
Complete history	<u>See info</u>



Registration #1	2008-11-27	28 mi
Registration #2	2011-11-01	22.052 mi
Registration #3	2013-03-04	35.132 mi
Registration #4	2014-04-15	46.527 mi
Registration #5	2015-04-23	54.282 mi
Registration #6	2015-04-24	54.304 mi
Registration #7	2016-04-26	63.773 mi
Registration #8	2017-04-20	71.158 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 esi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

CarCheck.co.uk

Video

see crash video



Dimensions & weight	
Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1486 kg
Max. allowed weight	1940 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	BKD C39550