





report date: 2024-03-29

#### General information

Make	BMW
Model	3 SERIES 320D ED PLUS
Colour	Black
Year of manufacture	2016
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	8 speed automatic

### Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	85.6 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



VX16BUU

report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



**MOT** history

MOT expiry date	2025-05-21
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	23
Total items failed	2

MOT #9		2024-04-22 15:01
MOT test	number	171152611964
Result		✓ Passed
Next expi	ry date	2025-05-21
Advice	Front 2x MacPherson strut dust cover damaged	
Advice Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))		
Advice	Oil leak, but not excessive rocker cover gasket (8.4.1 (a) (i))	
Advice	Nearside Rear shock absorber bump stop worn	
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))	

CarCheck.co.uk page 3/12



MOT #8 2024-04-22 10:15

MOT test number 150924442386

**Result** X Failed

**MAJOR** Offside Drag link end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Front 2x MacPherson strut dust cover damaged

**MAJOR** Offside Headlamp aim too high (4.1.2 (a))

Advice Oil leak, but not excessive rocker cover gasket (8.4.1 (a) (i))

Advice Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

**MAJOR** Nearside Drag link end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Nearside Front Nail in tyre

**MAJOR** Nearside Headlamp aim too high (4.1.2 (a))

**Advice** Nearside Rear shock absorber bump stop worn

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

**MOT #7** 2023-05-22 09:14

MOT test number 196061560462

Result \( \sqrt{Passed} \)

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2023-05-22 08:50

**MOT test number** 577762395672

**Result** X Failed

**DANGEROUS** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



VX16BUU

report date: 2024-03-29

MOT #5	2022-04-27 10:47
MOT test number	509476879737
Result	✓ Passed
MOT #4	2021-05-20 13:34
MOT test number	924092963369
Result	✓ Passed
MOT #3	2020-02-24 15:53
MOT test number	114047507012
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2020-02-24 15:53
MOT test number	615524714636
Result	<b>X</b> Failed
Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification Offside Headlamp aim too high (4.1.2 (a))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1	2019-02-15 12:31
MOT test number	775084016187
Result	✓ Passed

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	21 May 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



VX16BUU

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	
*********	
***************************************	
***********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-03
Last registration	2024-04-22
Complete history	See info



Registration #1	2016-03-03	25 mi
Registration #2	2019-02-15	95.300 mi
Registration #3	2020-02-24	122.373 mi
Registration #4	2020-02-24	122.373 mi
Registration #5		11.777 es
Registration #6	2021-05-20	133.442 mi
Registration #7		11.777 es
Registration #8		11.777 ea
Registration #9		9.77 es
Registration #10		0.074
Registration #11		10.707 au

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



## Dimensions & weight

Width	1811 mm
Height	1416 mm
Length	4633 mm
Wheel base	2810 mm
Kerb weight	1430 kg
Max. allowed weight	1980 kg

# Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 53399461