



report date: 2024-03-29

General information

|                     |                                  |
|---------------------|----------------------------------|
| Make                | VOLKSWAGEN                       |
| Model               | CC TDI BLUEMOTION TECHNOLOGY DSG |
| Colour              | Grey                             |
| Year of manufacture | 2012                             |
| Top speed           | 132 mph                          |
| 0 - 100 km/h        | 9.8 seconds                      |
| 0 - 60 mph          | 9.8 seconds                      |
| Gearbox             | 6 speed Semi Auto                |

Engine & fuel consumption

|                         |                           |
|-------------------------|---------------------------|
| Power                   | 103 kW / 140 HP / 138 BHP |
| Max. torque             | 320 Nm at 1.750 rpm       |
| Engine capacity         | 1.968 cc                  |
| Cylinders               | 4                         |
| Fuel type               | Diesel                    |
| Consumption city        | 44.1 mpg                  |
| Consumption extra urban | 60.1 mpg                  |
| Consumption combined    | 53.3 mpg                  |
| CO2 emission            | 139 g/km                  |
| CO2 label               | E                         |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-01                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: [autotrader.co.uk](#)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2022-07-27 |
| MOT pass rate      | 64 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 4          |
| Total advice items | 15         |
| Total items failed | 7          |

|                  |                  |
|------------------|------------------|
| MOT #11          | 2021-07-12 14:16 |
| MOT test number  | 908108393467     |
| Result           | ✓ Passed         |
| Next expiry date | 2022-07-27       |

|                 |   |
|-----------------|---|
| MOT #10         | 2021-07-09 10:17  |
| MOT test number | 484184431388  |
| Result          | ✗ Failed  |
| Fail            | Front Passenger's airbag obviously inoperative (7.1.5 (c))                |
| Fail            | Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) |
| Fail            | Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))        |

|                 |                        |
|-----------------|------------------------|
| MOT #9          | 2020-07-28 09:56       |
| MOT test number | 228194615084           |
| Result          | ✓ Passed               |
| Advice          | Emissions not detected |

**MOT #8** 2020-07-28 09:56**MOT test number** 269575130280**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Emissions not detected**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MOT #7** 2019-07-19 11:08**MOT test number** 708494609593**Result** ✓ Passed**MOT #6** 2018-08-01 15:53**MOT test number** 914800561716**Result** ✓ Passed**Advice** Both rear tyre treads distorted on inner edges**Advice** Nearside Front Tyre has a large cut in outer sidewall - no cords.**Advice** Deep cuts in both rear tyre treads**MOT #5** 2018-08-01 08:34**MOT test number** 193676097415**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre has a large cut in outer sidewall - no cords.**Advice** Deep cuts in both rear tyre treads**Advice** Offside Front Tyre is wearing on inner edge.**Advice** Both rear tyre treads distorted on inner edges

**MOT #4** 2017-03-06 11:50**MOT test number** 271864318453**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inner edge 235/40/18 (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit inner edge 235/40/18 (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit inner edge 235/40/18 (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit inner edge 235/40/18 (4.1.E.1)**MOT #3** 2016-02-27 13:19**MOT test number** 201847464499**Result** ✓ Passed**MOT #2** 2016-02-27 13:19**MOT test number** 181129408444**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2015-03-13 09:20**MOT test number** 667102975089**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕  
Untaxed

Tax expired:  
9 September 2021

✕  
MOT

Expired:  
27 July 2022

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 9 September          |
| Days left        | 964 days too late               |
| MOT expiry date  | 27 July 2022                    |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 49         |
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-06-29 |
| Current registration | *****      |
| Plate since          | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2012-03-14               |
| Last registration          | 2021-07-12               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2012-03-14 | 13 mi      |
| Registration #2  | 2015-03-13 | 36.312 mi  |
| Registration #3  | 2016-02-27 | 48.991 mi  |
| Registration #4  | 2016-02-27 | 48.991 mi  |
| Registration #5  | 2017-03-06 | 60.694 mi  |
| Registration #6  | 2018-08-01 | 80.638 mi  |
| Registration #7  | 2018-08-01 | 80.689 mi  |
| Registration #8  | 2019-05-29 | 91.277 mi  |
| Registration #9  | 2019-05-29 | 91.277 mi  |
| Registration #10 | 2019-05-29 | 91.277 mi  |
| Registration #11 | 2019-05-29 | 91.277 mi  |
| Registration #12 | 2019-05-29 | 91.277 mi  |
| Registration #13 | 2021-07-12 | 130.000 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 91%                             |
| Children       | 77%                             |
| Pedestrian     | 54%                             |
| Safety systems | 71%                             |
| Overall rating | 79%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2090 mm |
| Height              | 1421 mm |
| Length              | 4902 mm |
| Wheel base          | 2710 mm |
| Kerb weight         | 1564 kg |
| Max. allowed weight | 2070 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |

|                 |            |
|-----------------|------------|
| Number of seats | 5          |
| Number of axles | 2          |
| Engine number   | CFFB817289 |