




report date: 2024-02-25

General information

Make	MINI
Model	COUNTRYMAN COOPER AUTO COOPER
Colour	Red
Year of manufacture	2011
Top speed	113 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	H





## Internet history

### Entry 1

Date	2022-02-22
Pictures	39
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2025-04-01
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #12	2024-04-02 10:14
MOT test number	463243697406
Result	✓ Passed
Next expiry date	2025-04-01

MOT #11	2023-03-22 14:23
MOT test number	467468892488
Result	✓ Passed
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases flexi pipe (6.1.2 (a))

MOT #10	2022-03-29 13:24
MOT test number	853947326171
Result	✓ Passed

MOT #9	2021-12-07 10:56
MOT test number	522750002566
Result	✓ Passed
<b>Advice</b>	Front tyres perishing



**MOT #8** 2020-12-08 12:02

**MOT test number** 643583772995

**Result** ✓ Passed

**MOT #7** 2019-12-06 14:38

**MOT test number** 627778626056

**Result** ✓ Passed

**MOT #6** 2018-12-06 11:29

**MOT test number** 677653022950

**Result** ✓ Passed

**MOT #5** 2017-12-07 16:55

**MOT test number** 134041803394

**Result** ✓ Passed

**MOT #4** 2016-11-24 17:45

**MOT test number** 836759809294

**Result** ✓ Passed

**MOT #3** 2015-11-23 17:20

**MOT test number** 549506568413

**Result** ✓ Passed

**MOT #2** 2014-11-21 14:27

**MOT test number** 195485724319

**Result** ✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Notice** Under-trays fitted obscuring some underside components



**MOT #1** 2014-11-21 12:52

**MOT test number** 957035824380

**Result** ✗ Failed

**Notice** Under-trays fitted obscuring some underside components

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
1 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	158
<b>MOT expiry date</b>	1 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-




**Damage history**

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra MINI salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info >**



**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>LC61TFE</b>
Plate since	2019-09-25
Current registration	<b>LC61TFE</b>
Plate since	2019-09-25

More info >



**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-07
Last registration	2024-04-02
Complete history	<a href="#">See info</a>



Registration #1	2011-12-07	18 mi
Registration #2	2014-11-21	27.516 mi
Registration #3	2014-11-21	27.516 mi
Registration #4	2015-11-23	33.893 mi
Registration #5	2016-11-24	36.751 mi
Registration #6	2017-12-07	38.827 mi
Registration #7	2018-12-06	40.291 mi
Registration #8	2019-05-01	41.277 mi
Registration #9	2019-05-01	41.277 mi
Registration #10	2019-05-01	41.277 mi
Registration #11	2019-05-01	41.277 mi
Registration #12	2019-05-01	41.277 mi
Registration #13	2019-05-01	41.277 mi
Registration #14	2019-05-01	41.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1295 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	A192J105