



report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI SPORT
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





MOT history

MOT expiry date	2025-04-11
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	27
Total items failed	8

MOT #14 2024-04-12 10:33

MOT test number 174981527905

Result ✓ Passed

Next expiry date 2025-04-11

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13 2023-04-03 11:15

MOT test number 215267329580

Result ✓ Passed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated SMALL END SPLIT (6.1.7 (g) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated UPPER AND LOWER (5.3.4 (b) (i))

**MOT #12** 2022-01-14 13:18**MOT test number** 126662223943**Result** ✓ Passed**Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing TREADS CRACKING AND CUT (5.2.3 (d) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated CUT AT SMALL CLIP (6.1.7 (g) (i))**MOT #11** 2021-02-09 17:42**MOT test number** 841776307308**Result** ✓ Passed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #10** 2019-04-30 11:21**MOT test number** 835077875813**Result** ✓ Passed**MOT #9** 2019-04-23 06:04**MOT test number** 418571410001**Result** ✗ Failed**Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #8** 2018-10-29 16:21**MOT test number** 345802105387**Result** ✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear slight damage to the tyre outer sidewall
- Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #7 2018-10-29 14:48**MOT test number** 276178900347**Result** ✗ Failed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear slight damage to the tyre outer sidewall

MOT #6 2017-10-06 09:54**MOT test number** 155479982626**Result** ✓ Passed**MOT #5** 2016-09-26 11:03**MOT test number** 970039750851**Result** ✓ Passed

**MOT #4** 2015-10-02 14:11**MOT test number** 814183108750**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-02-27 07:53**MOT test number** 296288555024**Result** ✓ Passed**MOT #2** 2015-02-25 15:35**MOT test number** 669406755057**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-08-08 14:14**MOT test number** 397830723451**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-06
Last registration	2024-04-12
Complete history	See info



Registration #1	2010-07-06	22 mi
Registration #2	2013-08-08	42.609 mi
Registration #3	2015-02-25	44.122 mi
Registration #4	2015-02-27	44.122 mi
Registration #5	2015-10-02	48.567 mi
Registration #6	2016-09-26	56.522 mi
Registration #7	2017-10-06	64.210 mi
Registration #8	2018-10-29	70.731 mi
Registration #9	2019-05-20	75.000 mi
Registration #10	2019-05-20	75.000 mi
Registration #11	2019-05-20	75.000 mi
Registration #12	2019-05-20	75.000 mi
Registration #13	2019-05-20	75.000 mi
Registration #14	2019-05-20	75.000 mi
Registration #15	2019-05-20	75.000 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1424 mm
Length	4238 mm
Wheel base	2578 mm
Kerb weight	1430 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	CAY 633036