



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ2
Colour	Blue
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-04-25
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	7
Total items failed	1

MOT #10	2024-04-23 14:25
MOT test number	684708375516
Result	✓ Passed
Next expiry date	2025-04-25
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9	2023-04-26 08:20
MOT test number	732873791098
Result	✓ Passed

MOT #8	2022-02-21 15:58
MOT test number	132659558938
Result	✓ Passed

MOT #7	2020-12-02 12:47
MOT test number	907893101082
Result	✓ Passed

**MOT #6** 2019-08-29 10:50**MOT test number** 474142218184**Result** ✓ Passed**Advice** Nearside Rear Tyre perished 155 65 14**MOT #5** 2018-08-24 10:59**MOT test number** 631130500269**Result** ✓ Passed**MOT #4** 2018-08-17 08:51**MOT test number** 731901076826**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MOT #3** 2017-08-26 11:06**MOT test number** 952748481035**Result** ✓ Passed**MOT #2** 2016-09-21 14:06**MOT test number** 246611224527**Result** ✓ Passed**MOT #1** 2014-12-08 12:22**MOT test number** 446432644304**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
25 April 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	25 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-09-20
Last registration	2024-04-23
Complete history	<a href="#">See info</a>



Registration #1	2011-09-20	27 mi
Registration #2	2014-12-08	21.523 mi
Registration #3	2016-09-21	26.618 mi
Registration #4	2017-08-26	34.019 mi
Registration #5	2018-08-17	41.641 mi
Registration #6	2018-08-24	41.852 mi
Registration #7	2019-05-20	50.277 mi
Registration #8	2019-05-20	50.277 mi
Registration #9	2019-05-20	50.277 mi
Registration #10	2019-05-20	50.277 mi
Registration #11	2019-05-20	50.277 mi
Registration #12	2019-05-20	50.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1412346