



**YS55VNF**

report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Silver
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	313 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.7 mpg





Internet history

Entry 1

Date	2021-06-11
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #17</b>	2020-11-23 13:21
<b>MOT test number</b>	435405523184
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-11-24

<b>MOT #16</b>	2019-05-25 12:04
<b>MOT test number</b>	595225138602
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2018-04-18 10:07
<b>MOT test number</b>	446382024599
<b>Result</b>	✓ Passed

**Advice** Nearside Front Brake hose has slight corrosion to ferrules at front (3.6.B.4e)

**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

<b>MOT #14</b>	2017-04-06 16:20
<b>MOT test number</b>	706762366061
<b>Result</b>	✓ Passed

**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

**Advice** Offside Brake hose has slight corrosion to ferrules front area body to chassis (3.6.B.4e)

**Advice** Power steering component(s) has slight seepage from a component both sides of rack (2.3.3b)

**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

<b>MOT #13</b>	2016-04-19 12:21
<b>MOT test number</b>	159545951190
<b>Result</b>	✓ Passed

**MOT #12** 2015-04-17 13:23**MOT test number** 219517905494**Result** ✓ Passed**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #11** 2014-03-26 09:29**MOT test number** 756665684092**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2013-04-18 17:12**MOT test number** 917068003109**Result** ✓ Passed**MOT #9** 2013-04-16 09:10**MOT test number** 546506203108**Result** ✗ Failed**Advice** Offside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Brake pipe inadequately clipped (3.6.B.1)**Fail** Nearside Brake pipe excessively corroded (3.6.B.2c)**MOT #8** 2012-04-26 17:42**MOT test number** 227947912188**Result** ✓ Passed

**MOT #7** 2011-12-29 13:51**MOT test number** 276833361339**Result** ✓ Passed**MOT #6** 2011-12-29 09:40**MOT test number** 896103761353**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Fail** Registration plate character(s) incorrectly spaced (6.3.4a)**MOT #5** 2010-12-29 16:34**MOT test number** 280823060360**Result** ✓ Passed**Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2010-12-29 10:49**MOT test number** 590183460361**Result** ✗ Failed**Fail** Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Headlamp aim too low (1.8)**MOT #3** 2009-12-30 17:12**MOT test number** 364454069353**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2008-12-29 14:40
MOT test number	941354368304
Result	✓ Passed

MOT #1	2008-12-29 14:40
MOT test number	450614368410
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low and too far to the right. (1.8)
Pass with rectification	Offside Headlamp aim too low (1.8)
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>YS55VNF</b>
Plate since	2019-09-29
Current registration	<b>YS55VNF</b>
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-01-20
Last registration	2020-11-23
Complete history	<a href="#">See info</a>



Registration #1	2006-01-20	13 mi
Registration #2	2008-12-29	24.852 mi
Registration #3	2009-12-30	32.113 mi
Registration #4	2010-12-29	38.900 mi
Registration #5	2010-12-29	38.900 mi
Registration #6	2011-12-29	45.404 mi
Registration #7	2011-12-29	45.404 mi
Registration #8	2012-04-26	47.613 mi
Registration #9	2013-04-16	52.865 mi
Registration #10	2013-04-16	52.865 mi
Registration #11	2013-04-16	52.865 mi
Registration #12	2013-04-16	52.865 mi
Registration #13	2013-04-16	52.865 mi
Registration #14	2013-04-16	52.865 mi
Registration #15	2013-04-16	52.865 mi
Registration #16	2013-04-16	52.865 mi
Registration #17	2013-04-16	52.865 mi
Registration #18	2013-04-16	52.865 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2079 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB5840937