



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVA SE AC
Colour	Grey
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	95 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B






Internet history

Entry 3


Date	2024-04-27
Pictures	44
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-06-20
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 1

Date	2021-06-17
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-29
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	3
Total items failed	6

MOT #7	2023-06-13 12:28
MOT test number	980273502019
Result	✓ Passed
Next expiry date	2024-06-29
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6	2022-06-23 14:25
MOT test number	212153629490
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2022-06-23 14:25
MOT test number	486537555341
Result	✗ Failed
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4	2021-06-08 08:00
MOT test number	974109142119
Result	✓ Passed



MOT #3	2021-06-08 08:00
MOT test number	705974286631
Result	✗ Failed
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #2	2020-06-09 07:54
MOT test number	691503488280
Result	✓ Passed

MOT #1	2019-06-11 09:29
MOT test number	403862918490
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
26 April 2024

✓

MOT

Expires:
29 June 2024

Tax status	Expired at 26 April 2024
Days left	2 days too late
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2023-03-29
Current registration	 XXXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-06-30
Last registration	2023-06-13
Complete history	See info



Registration #1	2016-06-30	11 mi
Registration #2	2019-06-11	5.201 mi
Registration #3	2020-06-09	6.975 mi
Registration #4	2021-06-08	8.282 mi
Registration #5	2021-06-08	8.282 mi
Registration #6	2022-06-08	10.201 mi
Registration #7	2022-06-08	10.201 mi
Registration #8	2022-06-08	10.201 mi
Registration #9	2022-06-08	10.201 mi
Registration #10	2022-06-08	10.201 mi
Registration #11	2023-06-13	10.201 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	1876 mm
Height	1485 mm
Length	3675 mm
Wheel base	2385 mm
Kerb weight	864 kg
Max. allowed weight	1353 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	L5Q 162040084L5Q