





report date: 2024-03-29

## General information

Make	RENAULT	
Model	MEGANE DYNAMIQUE TOMTOM DCI	
Colour	Grey	
Year of manufacture	2012	
Top speed	118 mph	
0 - 60 mph	12.1 seconds	
Gearbox	6 speed Manual	

## Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



# Internet history

#### Entry 1

Date 2021-07-31

Pictures 40

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2023-07-15
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	14
Total items failed	3

MOT #11	2022-07-09 08:48
MOT test number	837006047988
Result	<b>✓</b> Passed
Next expiry date	2023-07-15

MOT #10	2021-07-16 15:50
MOT test number	316280178998
Result	<b>✓</b> Passed
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #9	2020-12-02 10:35
MOT test number	592727160885
Result	✓ Passed
MOT #8	2020-02-26 15:30

MOT test number	999043959212
Result	<b>✓</b> Passed

MOT #7	2018-05-25 13:56
MOT test number	260140656464
Result	<b>✓</b> Passed
Advice Child Seat fitted not allowing full inspection of adult belt 2 x	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

661030734394

Result

Advice Child Seat fitted not allowing full inspection of adult belt 2 x

Fail Rear Reversing lamp light intensity significantly reduced (4.6.2 (a))

**MOT #5** 2018-05-08 08:20 **MOT** test number 608538818029 Result **X** Failed Oil leak **Advice** Fail Nearside Rear coil spring broken (2.4.C.1a) Advice Offside Front Front wheel bearing has slight play (2.5.A.3c) Coolant leak Advice Advice Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a) **Advice** Child Seat fitted not allowing full inspection of adult belt X2

MOT #4	2017-04-27 11:58
MOT test number	691064947464
Result	✓ Passed
Advice Nearside Rear tyre perished	
Advice Offside Rear tyre perished	

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #3 2017-04-20 10:37

**MOT test number** 695387791748

**Result** X Failed

**Advice** Offside Rear tyre perished

**Fail** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Nearside Rear tyre perished

MOT #2 2016-04-19 09:30

**MOT test number** 774117623886

**Result** ✓ Passed

MOT #1 2015-04-24 12:51

MOT test number 959244615191

**Result** ✓ Passed

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**Notice** Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. ober of plates furthe scinors

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-04-30
Last registration	2022-07-09
Complete history	See info



Registration #1	2012-04-30	24 mi
Registration #2	2015-04-24	64.821 mi
Registration #3	2016-04-19	77.285 mi
Registration #4	2017-04-20	79.704 mi
Registration #5	2017-04-27	79.741 mi
Registration #6	2018-05-08	81.858 mi
Registration #7	2018-05-25	81.859 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 ms
Registration #12		0.00 44
Registration #13		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin

The RENAULT factory car options list is only available in the premium report.

S0225 Air conditioning

S0295

50482

\$0501 \$0566

S0567

S0569

View the complete RENAULT factory list for this vehicle <u>here</u>.

More info >

## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1795 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number D090924