



HYUNDAI



report date: 2024-10-06

General information

Make	HYUNDAI
Model	SONATA CRTD
Colour	Grey
Year of manufacture	2007
Top speed	124 mph
0 - 60 mph	11.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	304 Nm at 2.000 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	38.7 mpg
CO2 emission	191 g/km
CO2 label	J





## Internet history

### Entry 1

Date	2023-01-18
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-06
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	34
Total items failed	5

**MOT #18** 2023-11-07 14:27

**MOT test number** 582292832649

**Result** ✓ Passed

**Next expiry date** 2024-11-06

- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17** 2023-09-27 14:42

**MOT test number** 819345224376

**Result** ✗ Failed

- Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Fuel tank leaking (6.1.3 (b) (i))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))



MOT #16 2022-10-01 09:19

MOT test number 202157581847

Result ✔ Passed

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))

MOT #15 2022-10-01 08:45

MOT test number 506912953758

Result ✘ Failed

- Fail** Offside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 2.5mm (5.2.3 (d) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))



MOT #14 2021-09-20 07:53

MOT test number 563269256349

Result ✔ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13 2020-09-24 09:50

MOT test number 630149319556

Result ✔ Passed

- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Front fog lamp damaged
- Advice** Light misting around fuel filter

MOT #12 2019-09-20 08:03

MOT test number 596755777202

Result ✔ Passed

- Advice** Nsf fog lamp unit damaged
- Advice** Unable to check nsr seat belt seat not in use



**MOT #11** 2018-09-24 07:43

**MOT test number** 555357951357

**Result** ✓ Passed

**MOT #10** 2017-09-29 11:27

**MOT test number** 156819266891

**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Tyre worn close to the legal limit tyres starting to castle (4.1.E.1)

**MOT #9** 2016-09-08 11:25

**MOT test number** 709948653513

**Result** ✓ Passed

**MOT #8** 2015-09-02 09:42

**MOT test number** 272953727619

**Result** ✓ Passed

**MOT #7** 2014-08-29 11:10

**MOT test number** 946711444202

**Result** ✓ Passed

**MOT #6** 2014-08-29 09:46

**MOT test number** 519151944245

**Result** ✗ Failed

- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



**MOT #5** 2013-08-23 14:12

**MOT test number** 497785933225

**Result** ✓ Passed

**Notice** Nearside front tyre wearing thin on both edges

**Notice** Offside rear tyre cracked and inner edge wearing thin

**Notice** Nearside front tyre has slight damage to outer sidewall

**MOT #4** 2012-09-01 09:53

**MOT test number** 368165942486

**Result** ✓ Passed

**MOT #3** 2011-08-30 14:11

**MOT test number** 567242141244

**Result** ✓ Passed

**MOT #2** 2010-09-01 16:11

**MOT test number** 563004140287

**Result** ✓ Passed

**MOT #1** 2010-09-01 10:59

**MOT test number** 392844340429

**Result** ✗ Failed

**Advice** Tyre worn close to the legal limit (4.1.E.1)

**Fail** Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 November 2025

✗  
**MOT**

**Expired:**  
6 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	357
<b>MOT expiry date</b>	6 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-






Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>YT57LPU</b>
Plate since	2019-09-29
Current registration	<b>YT57LPU</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	20
<b>First mileage registration</b>	2007-09-01
<b>Last registration</b>	2023-11-07
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2007-09-01	16 mi
<b>Registration #2</b>	2010-09-01	16.124 mi
<b>Registration #3</b>	2010-09-01	16.125 mi
<b>Registration #4</b>	2011-08-30	20.788 mi
<b>Registration #5</b>	2012-09-01	24.610 mi
<b>Registration #6</b>	2013-08-23	28.759 mi
<b>Registration #7</b>	2014-08-29	33.223 mi
<b>Registration #8</b>	2014-08-29	33.223 mi
<b>Registration #9</b>	2015-09-02	38.293 mi
<b>Registration #10</b>	2016-09-08	42.370 mi
<b>Registration #11</b>	2016-09-08	42.370 mi
<b>Registration #12</b>	2016-09-08	42.370 mi
<b>Registration #13</b>	2016-09-08	42.370 mi
<b>Registration #14</b>	2016-09-08	42.370 mi
<b>Registration #15</b>	2016-09-08	42.370 mi
<b>Registration #16</b>	2016-09-08	42.370 mi
<b>Registration #17</b>	2016-09-08	42.370 mi
<b>Registration #18</b>	2016-09-08	42.370 mi
<b>Registration #19</b>	2016-09-08	42.370 mi
<b>Registration #20</b>	2016-09-08	42.370 mi

[More info >](#)



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1475 mm
Length	4800 mm
Wheel base	2700 mm
Kerb weight	1613 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

**Number of axles**

2

**Engine number**

D4EA6977306