



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 VTR HDI
Colour	White
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #20</b>	2022-01-19 10:58
<b>MOT test number</b>	172784808814
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-01-18
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Service brake binding but not excessively both front (1.2.1 (f))

<b>MOT #19</b>	2021-01-05 15:46
<b>MOT test number</b>	458473281527
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

<b>MOT #18</b>	2020-11-05 15:37
<b>MOT test number</b>	961658154337
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Position lamp not working (4.2.1 (a) (ii))
<b>Fail</b>	Offside Front Seat belt damaged (7.1.2 (b) (i))
<b>Advice</b>	Nearside Front door handle insecure
<b>Fail</b>	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Front Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))

<b>MOT #17</b>	2019-04-27 09:03
<b>MOT test number</b>	792616164002
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear tyre inner edge in contact with arch liner

**MOT #16** 2019-04-25 15:15**MOT test number** 681361612956**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear tyre inner edge in contact with arch liner**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #15** 2018-04-30 11:05**MOT test number** 571471311682**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 1.6mm worn on edges (4.1.E.1)**MOT #14** 2018-04-30 08:18**MOT test number** 665549362271**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively Both (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit 1.6mm worn on edges (4.1.E.1)**MOT #13** 2016-10-27 16:02**MOT test number** 489235265482**Result** ✓ Passed**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)

**MOT #12** 2016-10-27 10:09**MOT test number** 141240859547**Result** ✗ Failed**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #11** 2015-10-23 15:00**MOT test number** 849542075828**Result** ✓ Passed**MOT #10** 2015-10-23 14:22**MOT test number** 802660414777**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #9** 2014-10-24 15:32**MOT test number** 476937494281**Result** ✓ Passed**MOT #8** 2014-10-24 12:20**MOT test number** 666717794283**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)

**MOT #7** 2013-11-18 09:26**MOT test number** 115072623313**Result** ✓ Passed**MOT #6** 2012-11-22 11:39**MOT test number** 458247722483**Result** ✓ Passed**MOT #5** 2012-11-21 16:01**MOT test number** 256626022311**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #4** 2011-12-07 09:13**MOT test number** 865971141321**Result** ✓ Passed

- Notice** O/s/f outer door handle insecure
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #3** 2011-12-06 11:45**MOT test number** 865120141303**Result** ✗ Failed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** O/s/f outer door handle insecure**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #2** 2011-01-05 13:15**MOT test number** 335255501089**Result** ✓ Passed**MOT #1** 2011-01-05 12:01**MOT test number** 125085901072**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>AX57EOW</b>
Plate since	2019-03-29
Current registration	<b>AX57EOW</b>
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-01-24
Last registration	2022-01-19
Complete history	<a href="#">See info</a>



Registration #1	2008-01-24	28 mi
Registration #2	2011-01-05	10.657 mi
Registration #3	2011-01-05	10.657 mi
Registration #4	2011-12-06	14.499 mi
Registration #5	2011-12-07	14.499 mi
Registration #6	2012-11-21	19.006 mi
Registration #7	2012-11-22	19.006 mi
Registration #8	2013-11-18	22.261 mi
Registration #9	2014-10-24	31.065 mi
Registration #10	2014-10-24	31.065 mi
Registration #11	2015-10-23	34.485 mi
Registration #12	2016-01-20	35.337 mi
Registration #13	2016-01-20	35.337 mi
Registration #14	2016-01-20	35.337 mi
Registration #15	2016-01-20	35.337 mi
Registration #16	2016-01-20	35.337 mi
Registration #17	2016-01-20	35.337 mi
Registration #18	2016-01-20	35.337 mi
Registration #19	2016-01-20	35.337 mi
Registration #20	2016-01-20	35.337 mi
Registration #21	2016-01-20	35.337 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1780 mm
Height	1555 mm
Length	4839 mm
Wheel base	2750 mm
Kerb weight	1498 kg
Max. allowed weight	2132 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYVD4071845