



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI
Colour	Black
Year of manufacture	2012
Top speed	117 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-05
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-05-31
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	55
Total items failed	7

MOT #12	2023-05-31 14:56
MOT test number	116822031156
Result	✓ Passed
Next expiry date	2024-05-31
Advice	General underbody corrosion
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-06-01 09:48
MOT test number	781047414248
Result	✓ Passed
Advice	Front Shock absorbers has light misting of oil N/S & O/S (5.3.2 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2022-05-31 14:03

**MOT test number**

892470025588

**Result****✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Shock absorbers has light misting of oil N/S & O/S (5.3.2 (b))**Fail** Front Tyre tread depth below requirements of 1.6mm N/S & O/S (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9**

2021-03-22 16:54

**MOT test number**

948833819058

**Result****✓ Passed****MOT #8**

2020-03-17 15:29

**MOT test number**

103883793035

**Result****✓ Passed****Advice** Offside Front Tyre getting low on tread**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Nearside Front Tyre getting low on tread**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn low on inner edge of tread**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Windscreen washer not working

**MOT #7** 2019-03-21 10:42**MOT test number** 630062951062**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2018-03-02 12:38**MOT test number** 730786132627**Result** ✓ Passed**Advice** Engine & Underbody covers fitted**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2017-03-10 10:15**MOT test number** 344839653322**Result** ✓ Passed**MOT #4** 2017-03-09 12:15**MOT test number** 886514509145**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #3

2016-03-11 17:35

MOT test number

674770635476

Result

✓ Passed

- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)
- Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Rear Nail in tyre
- Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)
- Advice

Nearside Front Wiper blade deteriorated
- Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2016-03-11 15:15**MOT test number** 632726249210**Result** ✗ Failed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Wiper blade deteriorated
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**MOT #1** 2015-02-26 14:55**MOT test number** 308007855060**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
31 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	31 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>HY12LVE</b>
Plate since	2019-03-28
Current registration	 <b>HY12LVE</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-01
Last registration	2023-05-31
Complete history	<a href="#">See info</a>



Registration #1	2012-03-01	28 mi
Registration #2	2015-02-26	29.713 mi
Registration #3	2016-03-11	38.588 mi
Registration #4	2016-03-11	38.589 mi
Registration #5	2017-03-09	47.906 mi
Registration #6	2017-03-10	47.906 mi
Registration #7	2018-03-02	59.420 mi
Registration #8	2019-05-29	59.420 mi
Registration #9	2019-05-29	59.420 mi
Registration #10	2019-05-29	59.420 mi
Registration #11	2019-05-29	59.420 mi
Registration #12	2019-05-29	59.420 mi
Registration #13	2019-05-29	59.420 mi
Registration #14	2019-05-29	59.420 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1761 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	109257K