



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VAUXHALL |
| Model | AGILA S |
| Colour | Black |
| Year of manufacture | 2011 |
| Top speed | 109 mph |
| 0 - 60 mph | 12.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 92 BHP |
| Max. torque | 118 Nm at 4.800 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 119 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-07-23 |
| Pictures | 13 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-08 |
| MOT pass rate | 83 % |
| MOT passed | 10 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #12 | 2023-07-19 14:10 |
| MOT test number | 933045927853 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-08 |

| | |
|-----------------|---|
| MOT #11 | 2023-07-19 11:33 |
| MOT test number | 477396809643 |
| Result | ✗ Failed |
| Fail | Parking brake efficiency below requirements (1.4.2 (a) (i)) |

| | |
|-----------------|------------------|
| MOT #10 | 2022-08-09 13:33 |
| MOT test number | 681923094554 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #9 | 2022-01-06 15:43 |
| MOT test number | 205249230179 |
| Result | ✓ Passed |
| Advice | Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) |

**MOT #8** 2021-01-14 17:35**MOT test number** 287599995788**Result** ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing smooth on inner edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing smooth on inner edge (5.2.3 (e))
- Advice** Rear tyres cracking slightly

MOT #7 2021-01-14 11:06**MOT test number** 978647625424**Result** ✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear tyres cracking slightly
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing smooth on inner edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing smooth on inner edge (5.2.3 (e))

MOT #6 2020-01-06 12:42**MOT test number** 993325224883**Result** ✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Both rear tyres cracking slightly

**MOT #5** 2019-01-14 12:11**MOT test number** 533792570050**Result** ✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear tyres perished slightly

MOT #4 2018-01-17 12:02**MOT test number** 964726522508**Result** ✓ Passed

- Advice** Both rear tyres side walls cracking

MOT #3 2016-12-21 12:06**MOT test number** 895619616722**Result** ✓ Passed**MOT #2** 2016-01-15 14:52**MOT test number** 664157397824**Result** ✓ Passed**MOT #1** 2015-01-21 11:25**MOT test number** 527051525068**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
8 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 8 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | AK61ZSN |
| Plate since | 2019-03-29 |
| Current registration | AK61ZSN |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2011-11-30 |
| Last registration | 2023-07-19 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-11-30 | 10 mi |
| Registration #2 | 2015-01-21 | 14.960 mi |
| Registration #3 | 2016-01-15 | 28.444 mi |
| Registration #4 | 2016-12-21 | 37.078 mi |
| Registration #5 | 2018-01-17 | 46.898 mi |
| Registration #6 | 2019-01-14 | 53.322 mi |
| Registration #7 | 2020-01-06 | 62.055 mi |
| Registration #8 | 2020-05-20 | 65.277 mi |
| Registration #9 | 2020-05-20 | 65.277 mi |
| Registration #10 | 2020-05-20 | 65.277 mi |
| Registration #11 | 2020-05-20 | 65.277 mi |
| Registration #12 | 2020-05-20 | 65.277 mi |
| Registration #13 | 2020-05-20 | 65.277 mi |
| Registration #14 | 2020-05-20 | 65.277 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1932 mm |
| Height | 1590 mm |
| Length | 3740 mm |
| Wheel base | 2360 mm |
| Kerb weight | 990 kg |
| Max. allowed weight | 1485 kg |

Additional information

| | |
|-----------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | 1331429 |