





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|---------------------------|
| Model | T-ROC SEL TSI 4MOTION DSG |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 134 mph |
| 0 - 100 km/h | 7.2 seconds |
| 0 - 60 mph | 7.2 seconds |
| Gearbox | 7 speed Semi Auto |

Engine & fuel consumption

| Power | 140 kW / 191 HP / 188 BHP |
|-------------------------|---------------------------|
| Max. torque | 320 Nm at 1.500 rpm |
| Engine capacity | 1.984 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 33.2 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 41.5 mpg |
| CO2 emission | 155 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

| | | 1 |
|---|------|---|
| ᆮ | HLIV | - |

| Lifety 1 | |
|---------------|-------------|
| Date | 2021-09-06 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

2021-07-17 09:48

MOT history

MOT #1

| MOT expiry date | 2024-07-30 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 3 |
| Total items failed | 0 |

| MOT #3 | 2023-07-25 08:48 |
|----------------------------------------------------------------------------------------|------------------|
| MOT test number | 150689123269 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-30 |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) | |

| MOT #2 | 2022-07-29 10:11 |
|-------------------------------------------------------------------------------------|------------------|
| MOT test number | 939551827830 |
| Result | ✓ Passed |
| Advice Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii)) | |

| MOT test number | 382502840035 |
|--------------------------------------------------------------------------------------------------|------------------------------|
| Result | ✓ Passed |
| Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cuts (5.2.3 (d) (i)) | cords couple of slight stone |

CarCheck.co.uk page 3/10



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 154 |
| MOT expiry date | 30 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | 1 |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

More info >

Owner history

| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere. | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| | |
| | |
| *************************************** | |
| | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | NE NE |
| Plate since | |
| Current registration | OK OK |
| Plate since | |

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2018-07-31 |
| Last registration | 2023-07-25 |
| Complete history | See info |



| Registration #1 | 2018-07-31 | 21 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-07-17 | 38.887 mi |
| Registration #3 | | 11.177 es |
| Registration #4 | | 77,777 66 |
| Registration #5 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 96% |
| Children | 87% |
| Pedestrian | 79% |
| Safety systems | 71% |
| Overall rating | 86% |
| Video | see crash video |



Dimensions & weight

| Width | 1819 mm |
|---------------------|---------|
| Height | 1573 mm |
| Length | 4234 mm |
| Wheel base | 2603 mm |
| Kerb weight | 1420 kg |
| Max. allowed weight | 1990 kg |

Additional information

| Fuel tank capacity | 55 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| CarChock co.uk | nago 10/10 |

CarCheck.co.uk page 10/10

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | CZPB091726 |