



RENAULT

HV55HPK

report date: 2024-03-29

General information

Make	RENAULT
Model	MODUS DYNAMIQUE 16V
Colour	Silver
Year of manufacture	2005
Top speed	114 mph
0 - 60 mph	12.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	150 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-12-31
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-29
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	34
Total items failed	10

MOT #22	2024-01-22 12:00
MOT test number	186766765145
Result	✓ Passed
Next expiry date	2025-01-29

MOT #21	2023-01-17 13:56
MOT test number	695871817866
Result	✓ Passed

MOT #20	2021-12-30 09:45
MOT test number	725937820746
Result	✓ Passed
Advice	Front Play in steering rack inner joint(s) both
Advice	Offside Front Track rod end slightly misaligned (2.1.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2020-12-30 16:32

MOT test number

848156024053

Result

✓ Passed

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Play in steering rack inner joint(s)**MOT #18**

2020-12-30 16:32

MOT test number

604314145358

Result

✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Play in steering rack inner joint(s)**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #17**

2019-07-30 15:10

MOT test number

227232851875

Result

✓ Passed

Advice Play in steering rack inner joint(s)**MOT #16**

2018-09-03 15:02

MOT test number

232779012838

Result

✓ Passed

Advice Play in steering rack inner joint(s)

**MOT #15** 2017-08-15 14:37**MOT test number** 798318292702**Result** ✓ Passed**Advice** Offside Inner Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)**Advice** Oil leak**MOT #14** 2017-08-15 10:49**MOT test number** 369813177753**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Inner Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)**Advice** Oil leak**MOT #13** 2016-08-23 13:37**MOT test number** 538606218371**Result** ✓ Passed**MOT #12** 2016-08-23 10:31**MOT test number** 186281686918**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit tyre worn 0 mm on outer edge (4.1.E.1)**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt drop link boot split (2.4.G.2)**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt cv boot insecure (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit worn on both edges (4.1.E.1)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt drop link boot split (2.4.G.2)

**MOT #11** 2015-08-03 14:41**MOT test number** 278145115248**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2014-08-21 09:05**MOT test number** 675333934298**Result** ✓ Passed**MOT #9** 2013-08-30 15:48**MOT test number** 307632043226**Result** ✓ Passed**MOT #8** 2013-08-30 10:28**MOT test number** 306502943293**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** High level brake light not work**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear rear brake recording little or no effort (3.7.B.5a)**MOT #7** 2012-05-08 10:58**MOT test number** 647829422192**Result** ✓ Passed

**MOT #6** 2011-11-11 12:04**MOT test number** 689165311356**Result** ✓ Passed**MOT #5** 2011-09-02 13:06**MOT test number** 659555841288**Result** ✗ Failed**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Steering system has slight free play detected at steering wheel (2.2.A.1b)**Fail** Offside Rear rear brake binding (3.7.B.1)**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #4** 2010-11-18 16:55**MOT test number** 291482320388**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2010-11-18 11:32**MOT test number** 482482120399**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2009-11-12 13:44
MOT test number	354116819334
Result	✓ Passed

MOT #1	2008-10-17 12:47
MOT test number	372141498476
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 January 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	29 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-10-26
Last registration	2024-01-22
Complete history	See info



Registration #1	2005-10-26	24 mi
Registration #2	2008-10-17	10.735 mi
Registration #3	2009-11-12	11.665 mi
Registration #4	2010-11-18	20.949 mi
Registration #5	2010-11-18	20.949 mi
Registration #6	2011-09-02	24.459 mi
Registration #7	2011-11-11	24.619 mi
Registration #8	2012-05-08	24.685 mi
Registration #9	2013-08-30	29.853 mi
Registration #10	2013-08-30	29.853 mi
Registration #11	2014-08-21	33.614 mi
Registration #12	2015-08-03	36.367 mi
Registration #13	2015-08-03	36.367 mi
Registration #14	2015-08-03	36.367 mi
Registration #15	2015-08-03	36.367 mi
Registration #16	2015-08-03	36.367 mi
Registration #17	2015-08-03	36.367 mi
Registration #18	2015-08-03	36.367 mi
Registration #19	2015-08-03	36.367 mi
Registration #20	2015-08-03	36.367 mi
Registration #21	2015-08-03	36.367 mi
Registration #22	2015-08-03	36.367 mi
Registration #23	2015-08-03	36.367 mi
Registration #24	2015-08-03	36.367 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1960 mm
Height	1589 mm
Length	3792 mm
Wheel base	2482 mm
Kerb weight	1205 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D010100