




report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2014
Top speed	119 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-09-25
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-09-14
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2022-09-06
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #6 2021-09-07 13:20

MOT test number 267484101340

Result ✓ Passed

Next expiry date 2022-09-06

- Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Front Items removed from driver's view prior to test

MOT #5 2021-09-07 13:20

MOT test number 372978560922

Result ✗ Failed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Front Items removed from driver's view prior to test
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))

**MOT #4** 2020-09-04 10:00**MOT test number** 127611093042**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))**Advice** Front Items removed from driver's view prior to test**MOT #3** 2019-08-30 14:15**MOT test number** 597684749566**Result** ✓ Passed**MOT #2** 2018-08-31 10:51**MOT test number** 681848367294**Result** ✓ Passed**MOT #1** 2017-09-02 08:05**MOT test number** 233931120802**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	NK64UOE
Plate since	2019-06-29
Current registration	NK64UOE
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-09-01
Last registration	2021-09-07
Complete history	See info



Registration #1	2014-09-01	13 mi
Registration #2	2017-09-02	25.282 mi
Registration #3	2018-08-31	35.910 mi
Registration #4	2019-08-30	47.043 mi
Registration #5	2020-09-04	55.139 mi
Registration #6	2021-09-07	55.139 mi
Registration #7	2021-09-07	55.139 mi
Registration #8	2021-09-07	55.139 mi
Registration #9	2021-09-07	55.139 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1936 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 305355K LNQ