





report date: 2024-03-29

General information

Make	BMW
Model	316 116D
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	2.000 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	118 g/km
CO2 label	С



CarCheck.co.uk page 1/13



Internet history

Entry 1

2021-08-08 Date **Pictures** 3

Listing price View report







source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT	history
-----	---------

MOT expiry date	2024-09-13
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	17
Total items failed	7

MOT #16	2023-08-17 16:07
MOT test number	349843605486
Result	✓ Passed
Next expiry date	2024-09-13
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #15	2022-09-14 11:53
MOT test number	153699760965
Result	✓ Passed
Advice All front and rear suspension components covered in black sealent	

MOT #14	2020-12-03 15:28
MOT test number	403475642869
Result	✓ Passed

MOT #13	2020-12-03 11:59
MOT test number	152356193489
Result	X Failed
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



MOT #12 2019-12-04 15:01

MOT test number 172040088723

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front registration plate damaged

Advice Nearside Front tyre worn bald on outer edge

MOT #11 2019-12-04 15:01

MOT test number 514500732917

Result X Failed

Pass with rectification Front Position lamp not working both (4.2.1 (a) (ii))

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front tyre worn bald on outer edge

Advice Front registration plate damaged

MOT #10 2018-12-05 15:10

MOT test number 158240240792

Result
✓ Passed

Advice Rear Prop shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))

MOT #9 2018-12-04 13:59

MOT test number 731588939551

Result X Failed

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail

Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Rear Prop shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))

CarCheck.co.uk page 4/13



Result

OY59YLA report date: 2024-03-29

× Failed

MOT #8 2017-12-06 15:52

MOT test number 680220459455

Result \rightarrow Passed

Advice Nearside Rear Upper Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #7 2017-12-06 10:34

MOT test number 732132111333

Advice Nearside Rear Upper Suspension arm has slight play in a ball joint (2.4.G.2)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6 2016-12-07 12:52

MOT test number 724142018157

Result ✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Slight bind to nearside front wheel

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2015-10-08 13:58

MOT test number 890180173151

Result \rightarrow Passed

MOT #4 2015-10-08 13:58

MOT test number 601165965870

Result X Failed

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #3

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

2014-09-17 10:43

946610764230

✓ Passed

trent transplant, nearing aim (crosseg,	
MOT #2	2013-09-19 10:39
MOT test number	257652163294
Result	✓ Passed
MOT #1	2012-09-26 14:34
MOT test number	998190172280
Result	✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check





Expires: 13 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Venicle class	73
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
manage of the same	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK UK
Flate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-10-10
Last registration	2023-08-17
Complete history	See info



Registration #1	2009-10-10	8 mi
Registration #2	2012-09-26	29.755 mi
Registration #3	2013-09-19	47.174 mi
Registration #4	2014-09-17	61.815 mi
Registration #5	2015-10-08	75.478 mi
Registration #6	2015-10-08	75.478 mi
Registration #7	2016-12-07	87.625 mi
Registration #8	2017-12-06	97.459 mi
Registration #9	2017-12-06	97.459 mi
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		91,700 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

page 12/13 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1748 mm
Height	1421 mm
Length	4239 mm
Wheel base	2660 mm
Kerb weight	1305 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	51	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 94687259