





report date: 2024-03-29

General information

Make	BMW
Model	X6 XDRIVE30D SE
Colour	White
Year of manufacture	2016
Top speed	143 mph
0 - 60 mph	6.7 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



Internet history

Entry 5

Date	2023-03-22	
Pictures	0	
Listing price	<u>View report</u>	

source: carcraft.co.uk

Entry 4

Date	2023-02-13
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 3

Date	2022-11-14
Pictures	0
Listing price	View report


source: carcraft.co.uk

Entry 2

Lifety 2	
Date	2022-09-26
Pictures	52
Listing price	<u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-11-13
Pictures	4
Listing price	<u>View report</u>

CarCheck.co.uk page 2/11









source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-02
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	2
Total items failed	5

MOT #7	2023-11-03 09:19
MOT test number	361645842579
Result	✓ Passed
Next expiry date	2024-11-02

MOT #6	2022-10-26 14:37
MOT test number	587094800926
Result	✓ Passed

2022-10-24 15:52
805342666080
X Failed

Fail Rear Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4	2022-01-20 17:03
MOT test number	310880089771
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2021-11-16 08:01

MOT test number 662923445359

Result X Failed

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Outer side wall (5.2.3 (d) (i))

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #2 2020-11-10 14:52

MOT test number 500373330004

Result \(\sqrt{Passed} \)

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2019-06-01 12:31

MOT test number 345352649207

CarCheck.co.uk page 4/11





Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	hictor.
UMMIAI	nisiaiv

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have?		
Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	<u>iere</u> .	

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	NK (NK	
Place since	UK	
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-05-31
Last registration	2023-11-03
Complete history	See info



Registration #1	2016-05-31	16 mi
Registration #2	2019-06-01	34.216 mi
Registration #3	2020-11-10	61.038 mi
Registration #4		11.777 es
Registration #5	2021-11-16	92.072 mi
Registration #6	2022-01-20	92.074 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		11.777 no

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1989 mm
Height	1702 mm
Length	4909 mm
Wheel base	2933 mm
Kerb weight	2065 kg
Max. allowed weight	2780 kg

Additional information

Fuel tank capacity	85 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 60379519