





report date: 2024-03-29

General information

Make	BMW
Model	X3 SPORT
Colour	Blue
Year of manufacture	2005
Top speed	129 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	192 BHP
Max. torque	245 Nm at 3.500 rpm
Engine capacity	2.494 сс
Cylinders	6
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	31.4 mpg
Consumption combined	23.7 mpg
CO2 emission	289 g/km
CO2 label	М



CarCheck.co.uk page 1/14



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-05-10
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	27
Total items failed	10

MOT #22	2023-05-05 09:37
MOT test number	965903231990
Result	✓ Passed
Next expiry date	2024-05-10

MOT #21	2022-05-11 14:44
MOT test number	124564654368
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #20	2022-05-07 09:35
MOT test number	372451952840
Result	X Failed
Fail Nearside Headlamp light source and lamp not compatible (4.1.4 (c))	
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Offside Headlamp light source and lamp not compatible (4.1.4 (c))	
Fail Nearside Headlamp aim too high (4.1.2 (a))	

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT #19 2021-05-07 10:24

MOT test number 864070957309

MOT #18 2020-09-28 11:16

MOT test number 830716648740

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17 2020-09-28 11:16

MOT test number 595525603620

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #16 2019-10-15 15:21

MOT test number 531682710533

Advice Handbrake performance is poor

MOT #15 2019-10-15 10:03

MOT test number 409739877390

Result X Failed

Fail Offside Rear Coil spring fractured or broken Broken (5.3.1 (b) (i))

Fail Nearside Rear Coil spring fractured or broken Broken (5.3.1 (b) (i))

Advice Handbrake performance is poor

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #14

MOT test number

247669117294

Result

Advice Engine oil leaks

MOT #13

MOT test number

996319384536

Result

Advice Nearside front outer door handle broken but opens the door

MOT #12

MOT test number

694007745547

Result

Advice Ns outer door handle is broken [but works]

MOT test number

Result

Advice Ns outer door handle is broken [but works]

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Outer sidewall (4.1.D.1a)

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #10		2015-10-13 12:53
MOT test	number	981433913247
Result		✓ Passed
Advice	Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Offside front tyre has deep cut on outer sidewall but inner cording not clearly	exposed at present
Advice	Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside front exterior door handle deteriorated but still operates correctly	
Advice	Inner steering rack joints have slight play	

MOT #9		2015-10-13 12:53
MOT test	number	120647652874
Result		× Failed
Advice	Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside front exterior door handle deteriorated but still operates correctly	
Advice	Inner steering rack joints have slight play	
Advice	Advice Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Offside front tyre has deep cut on outer sidewall but inner cording not clearly	exposed at present
Pass wit	h rectification Nearside Headlamp aim too low (1.8)	

MOT #8		2014-10-06 11:24
MOT test	number	739069574211
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Nearside Side repeater slightly discoloured (1.4.A.2f)	

CarCheck.co.uk page 5/14



Result

DX05ZTV

report date: 2024-03-29

✓ Passed

MOT #7	2013-10-07 16:53
MOT test number	268410783227
Result	✓ Passed
MOT #6	2012-10-18 12:48
MOT test number	929752992268
Result	✓ Passed
Advice Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5		2012-02-27 09:56
MOT test	number	365858852051
Result		✓ Passed
Notice	Offside front tyre wearing on inner edge	
Notice	Child seat fitted not allowing full inspection of adult belt	

MOT #4	2011-02-22 13:20
MOT test number	906543151044
Result	✓ Passed
MOT #3	2010-02-15 11:49
MOT test number	231276740051

MOT #2	2009-02-16 12:28
MOT test number	740637849035
Result	✓ Passed
Notice Offside front tyre wearing on inner edge	

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #1 2008-02-20 09:58

MOT test number 341551158076


Result ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	10 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e mier metery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
manage of the same	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-01
Last registration	2023-05-05
Complete history	See info



Registration #1	2005-03-01	13 mi
Registration #2	2008-02-20	31.052 mi
Registration #3	2009-02-16	40.169 mi
Registration #4	2010-02-15	49.076 mi
Registration #5	2011-02-22	56.435 mi
Registration #6	2012-02-27	63.405 mi
Registration #7	2012-10-18	67.058 mi
Registration #8	2013-10-07	72.831 mi
Registration #9	2014-10-06	80.557 mi
Registration #10	2015-10-13	83.784 mi
Registration #11	2015-10-13	83.784 mi
Registration #12	2016-10-17	87.235 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

				_			
ונו	men:	CIOT	nc -	λ.	WAI	α	ht.
וט	пеп	STUI	13	CX.	$VV \subset I$	ш	TTU.

Width	1853 mm
Height	1674 mm
Length	4565 mm
Wheel base	2795 mm
Kerb weight	1815 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20235869

CarCheck.co.uk page 14/14