



H3530WN

report date: 2024-03-29

General information

Make	FORD
Model	ESCORT RS TURBO
Colour	Red
Year of manufacture	1990
Top speed	128 mph
0 - 60 mph	8.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	132 BHP
Max. torque	24 Nm at 2.750 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-11
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	30
Total items failed	0

MOT #11	2024-04-12 11:35
MOT test number	768942236584
Result	✓ Passed
Next expiry date	2025-04-11

MOT #10	2024-03-09 12:14
MOT test number	292973794570
Result	✗ Failed
MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength under sill (5.3.6 (a) (i))	
MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))	
MAJOR Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced under sill (7.1.1 (a) (i))	

MOT #9	2023-04-28 14:05
MOT test number	720212145196
Result	✓ Passed
Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice Exhaust noisy (8.1.1 (a))	
Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	
Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced inner sill (6.1.1 (c) (i))	



MOT #8	2022-05-27 16:52
MOT test number	357927018538
Result	✓ Passed

MOT #7	2021-05-28 11:35
MOT test number	150801424784
Result	✓ Passed
Advice	Oil leak on engin
Advice	Car emits slight blue smoke

**MOT #6**

2021-05-14 08:05

MOT test number

481950531796

Result**✗ Failed**

- MAJOR** Nearside Rear Coil spring insecure (5.3.1 (a) (i))
- MAJOR** Central Front Exhaust emissions likely to be affected by an exhaust leak manifold (8.2.1.1 (b))
- MAJOR** Exhaust emissions carbon monoxide content excessive (8.2.1.2 (b))
- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Offside Front Steering locking device missing (2.1.3 (d))
- Advice** Front Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Central Rear brake cylinder bolt missing
- MAJOR** Offside Front Coil spring insecure (5.3.1 (a) (i))
- DANGEROUS** Nearside Rear Fuel pipe so insecure there is a risk of fire (6.1.3 (a) (ii))
- MAJOR** Offside Rear Coil spring insecure (5.3.1 (a) (i))
- MAJOR** Offside Front Headlamp aim too high and too far to the right. (4.1.2 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Central Front Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Oil leak on engine
- MAJOR** Nearside Front Coil spring insecure (5.3.1 (a) (i))

MOT #5

2020-02-13 17:39

MOT test number

670344488567

Result**✓ Passed**

- Advice** Play in the steering



MOT #4	2012-04-20 15:49
---------------	------------------

MOT test number	479541712165
------------------------	--------------

Result	✓ Passed
---------------	----------

- Notice** Underbody corroded and undersealed
- Notice** Bottom ball joint dust covers starting to corrode
- Notice** Slight play in steering

MOT #3	2007-01-19 16:04
---------------	------------------

MOT test number	814979717089
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2006-01-21 13:04
---------------	------------------

MOT test number	234561526008
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2005-09-09 13:36
---------------	------------------

MOT test number	731052455295
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 November
-------------------	------------------------

Days left	185
------------------	-----

MOT expiry date	11 April 2025
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	1990-08-24
Last registration	2024-04-12
Complete history	See info



Registration #1	1990-08-24	13 mi
Registration #2	2005-09-09	19.994 mi
Registration #3	2006-01-21	20.013 mi
Registration #4	2007-01-19	27.443 mi
Registration #5	2012-04-20	37.926 mi
Registration #6	2020-02-13	38.100 mi
Registration #7	2020-02-13	38.100 mi
Registration #8	2020-02-13	38.100 mi
Registration #9	2020-02-13	38.100 mi
Registration #10	2020-02-13	38.100 mi
Registration #11	2020-02-13	38.100 mi
Registration #12	2020-02-13	38.100 mi
Registration #13	2020-02-13	38.100 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1641 mm
Height	1308 mm
Length	4062 mm

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	LT79072